



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010137/Any3q2	
			Date: 06/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLV 2035D	Veh. Inspected	SLS 3512C
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203708/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	13/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ODYSSEY	c.c	2356
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JHMRC1880HC203478	Colour	SILVER
	Odometer	131205 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
	L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/10/2022	Inspection Date	26/10/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	