

Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 25.10.2022

JHMR C1880H C203478
Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,493.20	\$ 1,493.20
2	TAILGATE LOWER MOULDING <i>cracked</i>	1	\$ 295.40	\$ 295.40
3	TAILGATE INNER LOCK <i>crack</i>	1	\$ 189.40	\$ 189.40
4	TAILGATE LOWER LOCK <i>broken</i>	1	\$ 25.30	\$ 25.30
5	TAILGATE LAMP <i>kit cracked</i>	2	\$ 461.80	\$ 923.60
6	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 147.20	\$ 147.20
7	TAILGATE STOPPER <i>3 for 1</i>	2	\$ 8.50	\$ 17.00
8	TAILGATE HOLDER <i>3 for 1</i>	1	\$ 29.60	\$ 29.60
9	TAILGATE INNER BOARD <i>cracked</i>	1	\$ 392.40	\$ 392.40
10	TAILGATE WINDSCREEN MOULDING <i>crack</i>	1	\$ 214.20	\$ 214.20
11	TAILGATE DETECTOR <i>cracked</i>	1	\$ 195.20	\$ 195.20
12	TAILGATE DETECTOR WIRE HARNESS <i>broken</i>	1	\$ 498.70	\$ 498.70
13	TAILGATE BUZZLE <i>cracked</i>	1	\$ 180.40	\$ 180.40
14	TAILLAMP <i>broken</i>	2	\$ 821.40	\$ 1,642.80
15	REAR BUMPER <i>cracked</i>	1	\$ 657.20	\$ 657.20
16	REAR BUMPER RELECTOR <i>broken</i>	2	\$ 75.20	\$ 150.40
17	REAR BUMPER SIDE TOP GARNISH <i>broken</i>	2	\$ 189.30	\$ 378.60
18	REAR BUMPER SIDE RETAINER <i>crack</i>	2	\$ 52.40	\$ 104.80
19	REAR FENDER INNER TRIM <i>broken</i>	2	\$ 849.20	\$ 1,698.40
20	REAR END PANEL <i>crack</i>	1	\$ 598.20	\$ 598.20

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS3512C**
 MODEL : **HONDA ODYSSEY**
 DATE OF ACCIDENT : 12.10.2022
 TIME OF ACCIDENT : 19:20 HRS

21	REAR END PANEL TOP GARNISH <i>cul d</i>	1	\$ 151.60	\$ 151.60	✓
22	REAR FLOOR MATT <i>xlce m</i>	1	\$ 596.20	\$ 596.20	x.
23	REAR JACK COVER GARNISH <i>Me n</i>	1	\$ 203.40	\$ 203.40	x.

4142.60
3314.08

TOTAL PRICE \$ 10,783.20
 LESS 20% \$ 2,156.64
SUB TOTAL PRICE \$ 8,626.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>xlce m</i>	1	\$ 80.00	\$ 80.00	x
2	REAR BUMPER CLIP (SET) <i>Nce</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE WINDSCREEN SEALANT <i>3 x ce</i>	1	\$ 80.00	\$ 80.00	40
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
5	TAILLAMP CLIP (SET) <i>Nce m</i>	1	\$ 60.00	\$ 60.00	x.
6	REAR FENDER COWLING CLIP (SET) <i>3 x ce</i>	1	\$ 80.00	\$ 80.00	x
7	REAR FENDER INNER TRIM CLIP (SET) <i>3 x ce</i>	1	\$ 80.00	\$ 80.00	x.
8	REAR END PANEL SEALANT <i>Me m</i>	1	\$ 150.00	\$ 150.00	x
9	REAR FLOOR MATT CLIP (SET) <i>Me m</i>	1	\$ 80.00	\$ 80.00	x.
10	REAR JACK COVER GARNISH CLIP (SET) <i>Me n</i>	1	\$ 50.00	\$ 50.00	x
11	REVERSE SENSOR (4PCS) <i>3 x ce</i>	1	\$ 380.00	\$ 380.00	200

300

TOTAL \$ 1,180.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLS3512C**
MODEL : **HONDA ODYSSEY**
DATE OF ACCIDENT : 12.10.2022
TIME OF ACCIDENT : 19:20 HRS

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	X

TOTAL \$ 4,690.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,806.56
TOTAL LABOUR COST : \$ 4,690.00
TOTAL REPAIR COST : \$ 14,496.56

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian C
L/S 26/10/22
05 days

total: 5254.08

L/S: A.2K

1640