



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 131L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH (WCP)	DENTED	650.00	650.00
1	REAR DOOR LOWER GARNISH LH (WCP)	CUT	130.00	130.00
1	REAR DOOR LOWER SIDE GARNISH LH (WCP)	CUT	90.00	90.00
1	REAR FENDER WHEEL ARCH GARNISH LH (WCP)	MISSING	120.00	120.00
1	PETROL TANK DOOR (WCP)	NOT NECESSARY	195.00	-
1	REAR BUMPER (WCP)	TO REPAIR SEE LABOUR	500.00	-
1	REAR BUMPER SIDE RETAINER LH (WCP)	NOT NECESSARY	23.00	-
1	REAR BUMPER LOWER GARNISH (WCP)	CUT	130.00	130.00
1	REAR FENDER LH (REPAIR REFER TO LABOUR) (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
	COST PLUS 15%		275.70	168.00
			2,113.70	1,288.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	35.00	30.00
1	REAR RIM 18 INCH (SN)	CUT	800.00	700.00
			835.00	730.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER & REAR FENDER LH.		800.00	600.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		600.00	600.00
	TO REMOVE/REFIX/REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		60.00	30.00
	TO REMOVE AND REFIT/REPLACE REAR DOOR LH FITTING, TRIMMINGS, GARNISH, WINDOW GLASS AND LOCK MECHANISM.		120.00	50.00
	TO REMOVE AND REFIX REAR TYRE LH AND WHEEL BALANCING IN ORDER TO REPLACE REAR RIM LH.		50.00	30.00

Report Ref No. CS/LPC22010142/Eny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK AND ADJUST WHEEL COMPUTERIZE ALIGNMENT.		80.00	80.00
			1,710.00	1,390.00
	GRAND TOTAL		4,658.70	3,408.00
	RECOMMENDED COST OF REPAIRS			3,408.00
	LESS EXCESS			-500.00
	NETT LIABILITY			2,908.00

Report Ref No. CS/LPC22010142/Eny3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.