



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010143/Uvy3m4 Date: 06/04/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6276R	Veh. Inspected	SFM 7118J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/22/2035	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	12/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C200 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2050422R188252	Colour	GREY	
Odometer	76022 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40ZR18	PIRELLI	7 mm	
L/H Front Tyre	245/40ZR18	PIRELLI	7 mm	
R/H Rear Tyre	245/40ZR18	PIRELLI	7 mm	
L/H Rear Tyre	245/40ZR18	PIRELLI	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/10/2022	Inspection Date	14/10/2022	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	