

Our Job Ref No : 305532926

Date : 18/10/22

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr. Naz

Vehicle Reg No. : SH 8956Y

12.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- SMP1872E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,700.00
Final Lumpsum Repair cost \$1,700.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Naz LKK

Date : 30/11/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SH8956Y

Make: HYUNDAI

Model: IONIQ

Date: 10/12/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>BR</i>			\$ 459.40
10	REAR BUMPER CLIPS <i>del</i>			\$ 22.00
1	REAR BUMPER CENTRE MOULDING <i>Cut</i>			\$ 451.25
1	REAR BUMPER REFLECTOR LAMP LH <i>? X SVC</i>			\$ 41.45
1	TAIL LAMP LH <i>? X SVC</i>			\$ 935.40
1	ASSY BLIND SPOT RADAR LH <i>X NN</i>			\$ 1,784.40
1	REAR FENDER LH <i>X Repair</i>			\$ 1,768.30
1	REAR BUMPER SIDE BRACKET LH <i>BT</i>			\$ 55.80
SUB TOTAL				\$ 5,518.00
LESS 20%				\$ 1,103.60
DISCOUNTED TOTAL				\$ 4,414.40
1	REAR BUMPER RUBBER MAT <i>SAEC</i>			\$ 50.00
1	REAR FENDER PETROL STICKER			\$ 15.00
				\$ 65.00
Labour Charge				
PANEL BEATING				\$ 1,800.00
SPRAY PAINTING CHARGE				\$ 600.00
CHECK ALL LIGHTING				\$ 60.00
TUFF KOTE				\$ 60.00
REMOVE/ REFIX UPSHOLSTERY AND CUSHION RR				\$ 120.00
TOTAL LABOUR				\$ 1,890.00
ESTIMATE TOTAL				\$ 6,369.40

Nett
Nett

700
500
30
X NN
60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days.
C/S
Guey
12/10
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: