

Kc

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225

H/P 91082728

Fax : 64816131

Chew Wee Tiong
Blk 368 Tampines St 34
#07-53
Singapore 520368

Not available
11 By @ 3300h
Recovery After Repair
4 days

Vehicle No : SLX 7124 L
Make : Toyota Allion
Year : 2009

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid ✓	RM \$855.70	✓
1 pc	Rear boot lid inner lock	RM \$405.10	X
1 pc	Rear boot lid emblem " Allion " ✓	RM \$45.90	✓
1 pc	Rear boot lid emblem " Logo " ✓	RM \$38.20	✓
1 pc	Rear boot lid emblem " A 1.5 " ✓	RM \$22.70	✓
1 pc	Rear boot rubber	RM \$203.10	X
1 pc	Rear o/s tail-lamp ? photo.	my car \$550.70	✓
1 pc	Rear end panel ? photo	RM \$577.35	X
1 pc	Rear end panel inner garnish ? photo	RM \$195.20	X
1 pc	Rear bumper - Colour code ✓	RM \$1,045.95	✓
1 pc	Rear o/s bumper brackets ? photo	RM \$105.30	✓
1 pc	Rear o/s bumper side retainer ✓	RM \$85.60	✓
1 pc	✗ Rear bumper reinforcement ?	RM \$487.20	X
1 pc	✗ Rear o/s bumper reflector ?	RM \$105.10	X
		\$4,723.10	
Less 25 %		\$1,180.77	
		\$3,542.33	

S. Nett Item

1 pc	Rear reverse sensor ✓ photo	shop \$200.00	✓
10 pcs	Rear bumper clip ✓	\$2.50 RM \$25.00	✓
1 pc	Rear bumper top protector ✓	RM \$200.00	405h
1 pc	Rear bumper lower skirt ✓	CM \$550.00	✓
		\$975.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$750.00 500h

balance c/f \$5,267.33

SLX 7124 L

balance b/f \$5,267.33

Labour Charges

To putty & spray paint on rear accident affected portion.

\$750.00 7001

Check/reconnect wiring.

\$30.00 201

To spray anti rust on accident affected portion.

\$100.00 301

Total \$6,147.33

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: