



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22010149/Rqy3q2	
			Date: 20/02/2023	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 4838H	Veh. Inspected	SMV 4895M
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22003216MFCV	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	13/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY 2.0	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	MR053BK3106016133	Colour	GREY
	Odometer	179647 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45 R18	ROTALLA	6 mm
	L/H Front Tyre	235/45 R18	ROTALLA	6 mm
	R/H Rear Tyre	235/45 R18	ROTALLA	6 mm
	L/H Rear Tyre	235/45 R18	ROTALLA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/10/2022	Inspection Date	19/12/2022
	Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	