

Shiau Chan (LKKAuto)

**From:** Rasul (LKKAuto)  
**Sent:** Monday, 13 February 2023 4:09 PM  
**To:** SUR; CS A Team  
**Subject:** FW: SMV 4895M

**From:** sharon@sngahtee.com <sharon@sngahtee.com>  
**Sent:** Monday, 13 February 2023 4:08:23 pm (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Subject:** RE: SMV 4895M

Hi Rasul  
  
Confirm. Thanks.

Best Regards  
  
Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



**From:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Sent:** Monday, 13 February 2023 10:21 am  
**To:** Sharon Sng <sharon@sngahtee.com>  
**Subject:** Re: SMV 4895M

Hi Sharon,  
  
Kindly acknowledge

Best Regards,  
  
**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315  
  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

**From:** Rasul (LKKAuto)  
**Sent:** Friday, 10 February 2023 10:26 am  
**To:** Sharon Sng <[sharon@sngahtee.com](mailto:sharon@sngahtee.com)>  
**Subject:** SMV 4895M

Hi Mr Sharon,

refer to attachment

We will be advising our principal a cost of repair P/P \$400.00./- with 02 days of repair subject to their approval.

Kindly acknowledge

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*