

COMFORTDELGRO**ENGINEERING**

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305532925
Date : 15.10.2022

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHC7245D

Date of Accident : 12.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- GBB1513X
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (include advertisement stickers etc,if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$850.00
Final Lumpsum Repair cost \$850.00
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : Lump

Signature : NJ

Name : LIM T S

Name : GUO QIANG NAZ LKK

Tel : 62148398

Date : 14/12/2022

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE

LKK-

DATE: 12.10.2022

INSURANCE: INCOME (45)MODEL: Hyundai I40MVA: LIM T 8VEHICLE NO: SHC7245D - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper / <i>EC</i>	1		\$ 553.00
	Rear Bumper Under Cover <i>X AN</i>	1		\$ 228.00
	Rear Bumper Reinforcement <i>X SVC</i>	1		\$ 428.40
	Rear Bumper Reinforcement Brkt RH/LH <i>X AN</i>	2	\$ 80.40	\$ 160.60
	Rear Bumper Clips / <i>MA</i>	10	\$ 2.20	\$ 22.00
	SUB TOTAL			\$ 1,392.00
	LESS 20%			\$ 278.40
	DISCOUNTED TOTAL			\$ 1,113.60 <i>460</i>
	Reverse Sensors <i>X AN</i>	1		\$ 135.70 <i>S/NETT</i>
	S/NETT LESS 10%			\$ 13.57
	S/NETT TOTAL			\$ 122.13
	Rear Bumper Mat / <i>MA</i>	1		\$ 50.00 <i>NETT</i>
	SPARE PARTS TOTAL			\$ 1,285.73
	Labour Charge			
	Panel Beating			\$ 300.00 <i>280</i>
	Spray Painting Charge			\$ 300.00 <i>250</i>
	R/I Reverse Sensors			\$ 120.00 <i>40</i>
	TOTAL LABOUR			\$ 720.00 <i>1,080</i>
	ESTIMATE TOTAL			\$ 2,005.73

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*2 Days.**4/5**Gmo Ag**W/10**3pm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the vehicle after spray painting
- To display the vehicle for a further resurvey
- Parts price to be based on "Prejudice" basis
- No illegal modifications
- Supply of parts to be surveyed and is subject to the insurance company

Acknowledged

Signature

Date