

REPAIR ESTIMATE

LKK-

DATE: 12.10.2022

INSURANCE: INCOME (45)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHC7245D - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper / <i>ll</i>	1		\$ 553.00	
	Rear Bumper Under Cover <i>X an</i>	1		\$ 228.00	
	Rear Bumper Reinforcement <i>?</i>	1		\$ 428.40	
	Rear Bumper Reinforcement Brkt RH/LH <i>X an</i>	2	\$ 80.40	\$ 160.60	
	Rear Bumper Clips <i>na</i>	10	\$ 2.20	\$ 22.00	
	SUB TOTAL			\$ 1,392.00	
	LESS 20%			\$ 278.40	
	DISCOUNTED TOTAL			\$ 1,113.60	
	Reverse Sensors <i>X an</i>	1		\$ 135.70	S/NETT
	S/NETT LESS 10%			\$ 13.57	
	S/NETT TOTAL			\$ 122.13	
	Rear Bumper Mat <i>/ na</i>	1		\$ 50.00	NETT
	SPARE PARTS TOTAL			\$ 1,285.73	
	Labour Charge				
	Panel Beating			\$ 300.00	
	Spray Painting Charge			\$ 300.00	
	R/I Reverse Sensors			\$ 120.00	
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 2,005.73	

280
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
4/5
Gmo Ag
Vfio
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts price to be based on the information
- Third party survey to be on "Without Prejudice" basis
- No illegal repair to be carried out
- Supplemental survey to be carried out and is subject to approval by the insurance Company

Acknowledged by Repairer:

Signature:

Date: