

ASS. REC. BY: Taufik

REF:

CS/EQI22010151/Tqy3

ASSIGNMENT

2032 Feb.

202, Month

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 410810

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF 7697 L Yr Regn: 202, MonthType: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Mini Cooper c.c. 1598Colour: white A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 10432 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WMW 5432020T 314563Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ SRim / ☐ STD A/Rim orTyre Size: F: 195/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or L959

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 18/10/22Survey held at RyderDes. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$7350, 9 days. (Red \$11122.66, 60%)

Date/Time, File Pass to?

☐ : Preli. Report1) 22/05 Typist☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 9Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum 7350

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SKE 7697L

Model:

MINI COOPER

Accident Date : 4/10/22

30/3/2012 29/2/2032

Location : PIE (CHANGI) BEFORE UPP SERANGOON EXIT

3P:

GBB329T (EQ)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper	881.40		th ✓
2	10pcs	Rear bumper clips		30.00	re ✓
3	2pcs	Rear bumper screw clips		20.00	re ✓
4	1pc	Rear bumper lower diffuser	300.50		de ✓
5	8pcs	Rear bumper lower diffuser clips		80.00	2000 ✓
6	1pc	Rear bumper enforcement	451.40		bt ✓
7	1pc	Rear bumper o/s retainer	312.70		de ✓
8	2pcs	Rear reverse sensor		280 380.00	re ✓
9	2pcs	Rear reverse sensor wire harness		210.20	X 7 ✓
10	1pc	Rear end panel inner trim	253.50		X 7 ✓
11	4pcs	Rear end panel inner trim clips		16.00	X 5 ✓
12	1pc	Rear o/s tail lamp	478.20		cu ✓
13	1pc	Rear o/s tail lamp chrome	100.30		dis ✓
14	1pc	Rear o/s tail lamp panel	183.80		bt ✓
15	1pc	Rear o/s tail lamp seal	40.50		re ✓
16	1pc	Rear boot cover	1,174.40		Rx ✓
17	1pc	Rear boot cover weatherstrip	174.40		X 7 ✓
18	1pc	Rear boot cover emblem	81.50		re ✓
19	1pc	Rear boot cover 'cooper' emblem	72.70		re ✓
20	1pc	Rear boot cover inner trim	282.25		X 7 ✓
21	8pcs	Rear boot cover inner trim clips		80.00	X 7 ✓
22	1pc	Rear boot cover o/s shock absorber	264.50		X 7 ✓
23	1pc	Rear o/s fender chrome strip	120.40		Rx ✓
24	1pc	Rear o/s fender	1,236.80		re ✓
25	1pc	Rear o/s fender wheel arch	187.40		cut ✓
26	6pcs	Rear o/s fender wheel arch clips		60.00	re - 20 ✓
27	1 pc	Rear o/s fender wheel guard	177.90		th ✓
28	6 pcs	Rear o/s fender wheel guard clips		60.00	re - 20 ✓
29	1pc	Rear o/s & n/s fender inner trim	300.30		X 7 ✓
30	10pcs	Rear o/s & n/s fender inner trim clips		100.00	X 7 ✓
31	1pc	Rear o/s quarter glass sealant		80.00	re ✓
32	1pc	Rear o/s quarter glass moulding	90.20		re ✓
33	1 pc	Rear windscreen sealant		80.00	X 7 ✓
34	1 pc	Rear windscreen moulding	102.40		X 7 ✓
35	1 pc	Front bumper	896.70		de ✓
36	10 pcs	Front bumper clips		30.00	re ✓
37	1 pc	Front bumper lower diffuser	288.50		cut ✓
38	1 pc	Front bumper sponge	194.20		X 7 ✓
39	1 pc	Front bumper enforcement	596.70		bt ✓


40	2 pcs	Front bumper o/s & n/s retainer	216.40		X nn
41	1 pc	Front bumper grille (Lower)	196.60		22
42	1 pc	Front bumper grille (Lower) chrome	121.30		22
43	1 pc	Front grille	266.70		22
44	6 pcs	Front grille clips		60.00	320
45	1 pc	Front grille seal	206.90		X nn
46	2 pcs	Front o/s & n/s head lamp	1,696.80	o/s - 40	X 848.40
47	1 pc	Front o/s fog lamp	255.4		22
48	1 pc	Front o/s fog lamp garnish	87.9		22
49	1 pc	Condenser	1,428.80		X nn
50	1 pc	Front reg. no. plate		45.00	67
51	1 pc	Front reg. no. plate bracket		29.00	X NN
		Rear RH inner shield by - \$179.95	Sub Total:	13,720.35	1360.20 0.00
		Rear RH Reinforcement bracket by - \$80.20	10%	0%	10%
		6827.45	After Less %:	12,348.32	1360.20 0.00
		Labour 6144.70			
1		To dismantle damaged parts, straighten & welding.		1,800.00	1200
2		To spray painting.		1,400.00	1000
3		To remove & refit rear exhaust to facilitate repair		100.00	X nn
4		To remove & refit upholstery to facilitate repair		180.00	60
5		To remove & replace rear reverse sensor camera.		50.00	30
6		To remove and refit rear windscreen		150.00	X nn
7		To remove and refit rear o/s quarter glass		150.00	X 600
8		To remove and replace rear tail gate		120.00	X nn
9		To remove & replace condenser and top up gas		100.00	X nn
10		To check for fault code and re set electrical system.		280.00	1202
11		To check wiring.		100.00	30
12		To re seal anti rust.		100.00	40
		Sub Total:		4,530.00	2480
		Total:		18,238.52	
		After Less 20%:		14,590.81	

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Taufik 97495749
WP 18/10/22 2pm 09 days

taufik@lkkauto.com
4/5 Ready after repair
taufik@lkkauto.com



AL 8778 1999
24 hr accident call



PAYNOW

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6144.70
565
2480

9189.70
4887350
109 days