

Our Job Ref No : 305532924
Date : 15.10.2022

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Attn : GUO QIANG

Vehicle Reg No. : SHD4027G

Fax :

Date of Accident : 11.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- SLX 743X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,950.00

Final Lumpsum Repair cost \$1,950.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : GUO QIANG NAZ LKK

Date : 15/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Sc

COMFORTDELGRO ENGINEERING PTE LTD

✓ SAS-KIV → see attached
Effective Date: 1 Nov 2020REPAIR ESTIMATEDATE: 12.10.2022INSURANCE: INCOME (L/S)MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO: SHD4027GMVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH / RH	2	\$ 138.10	\$ 276.20
	Rear Bumper Side Brackets LH / RH	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH / RH	2	\$ 41.45	\$ 82.90
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper FogLamp	1		\$ 201.50
	Rear Smart Key Antenna	1		\$ 40.50
	BootLid Emblem - Hybrid	1		\$ 24.30
	BootLid Emblem - Ioniq	1		\$ 31.30
	SUB TOTAL		1,087.05	\$ 2,349.55
	LESS 20%			\$ 469.91
	DISCOUNTED TOTAL		869.64	\$ 1,879.64
	BootLid ComfortDelGro	1		\$ 30.00
	BootLid 65521111	1		\$ 30.00
	BootLid ZIG	1		\$ 40.00
	Reverse Sensors	1		\$ 180.00
	Rear No. Plate With Trim Cover	1		\$ 55.00
	S/NETT SUB			\$ 335.00
	LESS 10%			\$ 33.50
	S/NETT TOTAL			\$ 301.50
	Rear Bumper Mat	1		\$ 50.00
	BootLid Adv. Sticker	1		\$ 100.00
	Rear Fender Adv. Sticker	2	\$ 100.00	\$ 200.00
	SPARE PARTS TOTAL			\$ 2,531.14
	Labour Charge			\$ 800.00
	Panel Beating			\$ 600.00
	Spray Painting Charge			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 1,520.00
	TOTAL LABOUR			\$ 4,051.14
	ESTIMATE TOTAL			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.

1,928.91