

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
 Tel: 6453 8686 (3 Lines) Fax: 6459 6550
 Company Reg. No.: 201113667N
 GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z
 Accident Date : 13-Oct-2022

Our Ref : 022166 (LONPAC) / CHAN

LIM PUAY KOON
 BLK 103 RIVERVALE WALK
 #11-72
 Singapore 540103

Not Authorized
11 Rmp @ 28,200/r
Repair After Pain
16 days

No. : 06674
 Date : 15-Oct-2022
 PAGE : 1

ESTIMATED COST OF REPAIR FOR TOYOTA NOAH 1.8G CVT HYBRID SJM728Y

1 pc	Front windscreen glass		CM 2,159.30	✓
1 pc	Front w/s glass top moulding		NI M/CMA 85.90	✓
2 pcs	Front w/s pillar side moulding @	S\$128.70	257.40	2+
10 pcs	W/s pillar side moulding clip @	S\$ 11.80	118.00	2
1 pc	Front n/s wiper blade		GA 108.80	✓
1 pc	Front wiper garnish		Red 699.10	✓
2 pcs	Wiper garnish side cover <i>ols Pux</i>	@ S\$ 88.20	NI/SA 176.40	4
1 pc	Frt wiper garnish lower panel		Red 689.90	2
1 pc	Front dashboard		mtj CM 1,980.90	2
2 pcs	Front fender <i>ols Bu N/SBT</i>	@ \$1138.50	2,277.00	53811-28180 240
2 pcs	Front fender glass moulding	@ S\$243.50	487.00	2
2 pcs	Front fender side retainer	@ S\$120.50	241.00	4
2 pcs	Front fender "HYBRID" emblem	@ S\$ 68.70	137.40	✓
1 pc	Front n/s fender inner shield		CM 186.00	✓
1 pc	Bonnet		B 944.10	✓
2 pcs	Bonnet hinge	@ S\$ 68.70	B 137.40	✓
1 pc	Bonnet insulator		T 375.10	✓
5 pcs	Bonnet insulator clip	@ S\$ 3.80	Ne 19.00	✓
1 pc	Bonnet front rubber		T 34.70	✓
1 pc	Bonnet chrome		mi 538.00	✓
1 pc	Bonnet nozzle hose		Pin 45.10	X
1 pc	Bonnet nozzle hose clip		CM 34.80	2
1 pc	Bonnet stand clip		mi 24.50	✓
1 pc	Bonnet inner lock		mi 131.80	✓
1 pc	Front bumper fascia		T 676.60	✓
1 pc	Front bumper side bracket		B 105.50	✓
1 pc	Front grille - upper	1116.30	CM 1,296.30	✓
1 pc	Front grille logo		Ne 226.60	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
 Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N
 GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 2

1 pc	Front centre grille assy	655-10	CMA	1,221.80	✓
1 pc	Front lower grille		Sm	183.90	X
1 pc	Front bumper reinforcement		Pr	330.20	✓
1 pc	Front bumper sponge		CMA	85.90	✓
1 pc	Front n/s foglamp		Bro	516.00	✓
1 pc	Front n/s foglamp cover		nd	188.20	✓
1 pc	Front n/s foglamp bracket		Pr	77.80	✓
2 pcs	Headlamp assy	dis mg cma c3665.16 @ \$3680.80	Pr	7,361.60	N/S Bro ✓
2 pcs	Headlamp garish	n/s mis @ S\$ 67.40		134.80	✓
1 pc	N/s Headlamp socket holder		Pr	368.80	X
1 pc	Front support panel	53205-28200	Pr	1,908.40	✓
2 pcs	Front support side guide	n/s cma @ S\$ 54.30		108.60	✓
1 pc	Brace panel		n	101.20	X
1 pc	Front n/s wheel housing	1052-60	Pr	1,160.60	✓
1 pc	Wheel housing panel bracket(F)		Pr	51.10	✓
1 pc	Radiator assy	16400-37280	TT/Pr	2,469.60	✓
1 pc	N/s radiator stopper		mit	23.30	✓
1 pc	Radiator fan cowling		CMA	321.40	✓
1 pc	Radiator fan motor		Sm	794.30	X
1 pc	Radiator fan blade		CMA	294.70	✓
1 pc	Radiator spare tank		Sm	205.90	X
1 pc	Radiator top hose		Sm	55.80	X
1 pc	Radiator lowwr hose		Sm	96.80	X
1 pc	Air con condenser		TT	1,463.80	✓
1 pc	Air con fan motor		Sm	794.30	X
1 pc	Air con fan blade		Sm	236.20	X
1 pc	Inverter cooler		Pr	1,003.80	✓
1 pc	Inverter cooler hose		Sm	82.50	X
1 pc	Inverter assy		Pr / Sm	5,694.00	✓
1 pc	INverter coolant tank		nd	398.80	✓
1 pc	Inverter bracket		Pr	121.40	✓
1 pc	Inverter coolant tank hose		Sm	85.30	X
1 pc	Inverter top wire cover		Pr	222.30	✓
1 pc	N/s horn		nd	145.20	✓
1 pc	N/s fuse box top cover		nd	118.50	✓
1 pc	N/s fuse assy		CMA	271.30	✓
1 pc	N/s fuse holder		CMA	324.70	✓
1 pc	N/s fuse lower cover		CMA	107.60	✓

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 3

- 1 pc Resonator tank
- 1 pc Air cleaner housing assy

17700-37292

Sn 174.50 X
 CM 1,559.70

45,058.20
 Less 25% : 11,264.55

- 1 pc Front w/s glass sealant
- 1 pc ERP bracket
- 1 pc Front w/s glass solar film
- 1 pc Front bumper clip (set)
- 1 pc Radiator coolant
- 1 pc Inverter coolant
- 1 pc Cooler oil

33,793.65
 Mr 401N 60.00 sn
 Mr 201N 25.00 sn
 Mr 201N 350.00 sn
 Mr 25.00 sn
 Mr 30.00 sn
 Mr 15.00 sn
 Mr 10.00 sn

To towing

60.00 ✓

To rewire damaged parts and refocus headlamp beam.

120.00 80d

To remove & renew front windscreen glass and conduct water leak test.

150.00 120d

To remove air con condenser, pipes and drier, vacuum and to recharge gas

120.00 100d

To apply undersealing

100.00 90d

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

220.00 ✓

To dismantle and lower front undercarriage

300.00 180d

To check and adjust wheel alignment

65.00 60d

Con't Page 4 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 4

To remove and lift up engine assy.

2801
400.00

To putty and spray replaced parts

14001
1,800.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

18001
2,200.00

To rewire, diagnostic, programme,
reset inverter system

200.00 *✓*

Total : S\$40,043.65

Singapore Dollars Forty Thousand and Forty Three
and Cents Sixty Five Only