

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

*Not authorized*  
*11 Rep &*  
*Repair After Paint*  
*(6 days)*

No. : 06674

Vehicle Insured : GBC6363Z  
 Accident Date : 13-Oct-2022

Date : 15-Oct-2022

Our Ref : 022166 (LONPAC) / CHAN

PAGE : 1

LIM PUAY KOON  
 BLK 103 RIVERVALE WALK  
 #11-72  
 Singapore 540103

ESTIMATED COST OF REPAIR FOR TOYOTA NOAH 1.8G CVT HYBRID SJM728Y

1 pc Front windscreen glass		<i>CM</i>	2,159.30	✓
1 pc Front w/s glass top moulding		<i>NI</i>	85.90	✓
2 pcs Front w/s pillar side moulding	@ S\$128.70	<i>NI</i>	257.40	✓
10 pcs W/s pillar side moulding clip	@ S\$ 11.80	<i>NI</i>	118.00	✓
1 pc Front n/s wiper blade		<i>NI</i>	108.80	✓
1 pc Front wiper garnish		<i>NI</i>	699.10	✓
2 pcs Wiper garnish side cover	@ S\$ 88.20	<i>NI</i>	176.40	✓
1 pc Frt wiper garnish lower panel			689.90	?
1 pc Front dashboard			1,980.90	?
2 pcs Front fender	@ \$1138.50	<i>NI</i>	2,277.00	✓
2 pcs Front fender glass moulding	@ S\$243.50	<i>NI</i>	487.00	✓
2 pcs Front fender side retainer	@ S\$120.50	<i>NI</i>	241.00	✓
2 pcs Front fender "HYBRID" emblem	@ S\$ 68.70	<i>NI</i>	137.40	✓
1 pc Front n/s fender inner shield		<i>CM</i>	186.00	✓
1 pc Bonnet		<i>NI</i>	944.10	✓
2 pcs Bonnet hinge	@ S\$ 68.70	<i>NI</i>	137.40	✓
1 pc Bonnet insulator		<i>NI</i>	375.10	✓
5 pcs Bonnet insulator clip	@ S\$ 3.80	<i>NI</i>	19.00	✓
1 pc Bonnet front rubber		<i>NI</i>	34.70	✓
1 pc Bonnet chrome		<i>NI</i>	538.00	✓
1 pc Bonnet nozzle hose			45.10	?
1 pc Bonnet nozzle hose clip		<i>CM</i>	34.80	✓
1 pc Bonnet stand clip		<i>NI</i>	24.50	✓
1 pc Bonnet inner lock		<i>NI</i>	131.80	✓
1 pc Front bumper fascia		<i>NI</i>	676.60	✓
1 pc Front bumper side bracket		<i>NI</i>	105.50	✓
1 pc Front grille - upper		<i>CM</i>	1,296.30	✓
1 pc Front grille logo		<i>NI</i>	226.60	✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 2

1 pc	Front centre grille assy	CMA	1,221.80	✓
1 pc	Front lower grille	Sm	183.90	X
1 pc	Front bumper reinforcement		330.20	?
1 pc	Front bumper sponge	CMA	85.90	✓
1 pc	Front n/s foglamp	Bro	516.00	✓
1 pc	Front n/s foglamp cover	nd	188.20	✓
1 pc	Front n/s foglamp bracket	Br	77.80	✓
2 pcs	Headlamp assy <i>als mg cma</i>		7,361.60	n/s Bro ✓
2 pcs	Headlamp garish <i>n/s m/s</i>		134.80	✓
1 pc	N/s Headlamp socket holder		368.80	?
1 pc	Front support panel	Br	1,908.40	✓
2 pcs	Front support side guide <i>n/s cma</i>		108.60	✓
1 pc	Brace panel	R	101.20	X
1 pc	Front n/s wheel housing	Br	1,160.60	✓
1 pc	Wheel housing panel bracket(F)	Br	51.10	✓
1 pc	Radiator assy		2,469.60	?
1 pc	N/s radiator stopper	mit	23.30	✓
1 pc	Radiator fan cowling		321.40	?
1 pc	Radiator fan motor		794.30	?
1 pc	Radiator fan blade		294.70	?
1 pc	Radiator spare tank		205.90	?
1 pc	Radiator top hose		55.80	?
1 pc	Radiator lowewr hose		96.80	?
1 pc	Air con condenser	TT	1,463.80	✓
1 pc	Air con fan motor		794.30	?
1 pc	Air con fan blade		236.20	?
1 pc	Inverter cooler		1,003.80	?
1 pc	Inverter cooler hose		82.50	?
1 pc	Inverter assy		5,694.00	?
1 pc	INverter coolant tank		398.80	?
1 pc	Inverter bracket		121.40	?
1 pc	Inverter coolant tank hose		85.30	?
1 pc	Inverter top wire cover	DIY	222.30	✓
1 pc	N/s horn	nd	145.20	✓
1 pc	N/s fuse box top cover	nd	118.50	✓
1 pc	N/s fuse assy	CMA	271.30	✓
1 pc	N/s fuse holder		324.70	?
1 pc	N/s fuse lower cover		107.60	?

Con't Page 3 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 3

1 pc Resonator tank  
1 pc Air cleaner housing assy

174.50 7  
CM 1,559.70 ✓

45,058.20  
Less 25% : 11,264.55

1 pc Front w/s glass sealant  
1 pc ERP bracket  
1 pc Front w/s glass solar film  
1 pc Front bumper clip (set)  
1 pc Radiator coolant  
1 pc Inverter coolant  
1 pc Cooler oil

33,793.65  
No 60.00 sn  
No 25.00 sn ✓  
No 200.00 350.00 sn  
No 25.00 sn ✓  
No 30.00 sn ✓  
No 15.00 sn ✓  
No 10.00 sn ✓

To towing

60.00 ✓

To rewire damaged parts and refocus headlamp beam.

120.00 80

To remove & renew front windscreen glass and conduct water leak test.

150.00 120

To remove air con condenser, pipes and drier, vacuum and to recharge gas

120.00 100

To apply undersealing

100.00 90

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

220.00 ✓

To dismantle and lower front undercarriage

300.00 180

To check and adjust wheel alignment

65.00 60

Con't Page 4 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC6363Z

Page : 4

To remove and lift up engine assy.	280 400.00
To putty and spray replaced parts	1400 1,800.00
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1800 2,200.00
To rewire, diagnostic, programme, reset inverter system	200.00 7
Total :	----- S\$40,043.65 =====

Singapore Dollars Forty Thousand and Forty Three  
and Cents Sixty Five Only