

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22010155/UNY3Q2
Date: 22/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNW00132552201	
Claimant Vehicle No : FBT302A	Insured Vehicle No : SMT6344J	
Date of Loss: 08/10/2022	Nature of Claim: TP	Claim No: SNM22D207255/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBT302A	Engine No:	N515E027777
Make & Model:	YAMAHA YZF-R1, 998cc (M)	Chassis No:	JYARN191000021913
Reg. Date:	22/10/2009 (Man. Year: 2008)	Odometer:	91979 km
Colour:	Multi-colour		
Engine Capacity:	998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	190/55Z R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,970.00	2,686.50	10,283.50	79.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	450.00	350.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,770.00	3,136.50	10,633.50	77.22
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	13,770.00	2,500.00	11,270.00	81.84
+ GST 7.00/7.00% (S\$)	963.90	175.00	788.90	81.84
Nett Amount (S\$)	14,733.90	2,675.00	12,058.90	81.84

INSPECTION

Date of Assignment:	12/10/2022	
Date Inspected:	13/10/2022	Inspected At: Erzat Lee Motor Trading Pte Ltd (HQ) Synergy@KB 25, Kaki Bukit Road 4 #03-37 Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Nov 2022)	
Parts:	N/A	YAMAHA YZF-R1 998cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT302A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK	Repair	2,800.00 F	*- FL
2	1		*FORK -UNDER BRACKET	Not Necessary	1,500.00 F	*- FL
3	1		*STEERING CONE	Not Necessary	500.00 F	*- FL
4	1		*FRONT SPORT RIM ALIGNMENT	Not Necessary	350.00 F	*- FL
5	1		*FRONT SHAFT SLIDER	Cut	250.00 F	*80.00 FL
6	1		*HEAD LIGHT	Broken	1,800.00 F	*1,250.00 FL
7	1		*HEAD COVER	Cracked	500.00 F	*500.00 FL
8	1		*HEAD LAMP STAY	Not Necessary	700.00 F	*- FL
9	1		*N/S MIRROR	Cut	800.00 F	*165.00 FL
10	1		*AIR BOX	Cracked	300.00 F	*180.00 FL
11	1		*AIR BOX COVER	Cracked	150.00 F	*90.00 FL
12	1		*HANDLE BAR LEFT	Not Necessary	480.00 F	*- FL
13	1		*HANLE BAR END	Not Necessary	200.00 F	*- FL
14	1		*FRONT FAIRING COVER LEFT	Cut	480.00 F	*480.00 FL
15	1		*FRONT SIGNAL LEFT	Cracked	150.00 F	*80.00 FL
16	1		*SLIDER FAIRING	Cut	180.00 F	*80.00 FL
17	1		*FUEL TANK	Not Necessary	800.00 F	*- FL
18	1		*REAR SWING ARM SLIDER	Cut	200.00 F	*80.00 FL
19	1		*REAR FOOTREST LEFT	Serviceable	120.00 F	*- FL
20	1		*FRONT FOOTREST	Not Necessary	180.00 F	*- FL
21	1		*FRONT FOOTREST BRACKET	Not Necessary	350.00 F	*- FL
22	1		*GEAR PEDAL	Not Necessary	180.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,970.00	2,985.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	298.50
Total Parts (\$\$)	12,970.00	2,686.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	800.00	450.00
Gross Labour Cost (\$\$)			800.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >