



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010156/Avy3m4 Date: 30/11/2022 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PC 105B	Veh. Inspected	SMF 1710S	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS22/1288	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	12/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA AXIO	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	NZE1416112013	Colour	BLUE	
Odometer	183366 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	HABILEAD	6 mm	
L/H Front Tyre	195/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/10/2022	Inspection Date	13/10/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 09 MARCH 2009 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	