

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 24 Nov 2022

Preliminary Advice

Vehicle No	: SFJ96A	Accident Date	: 04/09/2022
Make	: PEUGEOT 3008	Policy No.	: DMPCSNA00151862202
Assignment Date	: 12/10/2022	Excess	: S\$500.00
Date of Inspection	: 14/10/2022	Est. Duration of Repair	: 14
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 50,266.70	(Estimate \$47,864.10 + Supplementary \$2,402.60)
Revised Amount	:S\$ 23,984.20	
Check Items (Estimated)	:S\$ 14,606.70	
Total	:S\$ 38,590.90	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	36,461.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,539.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.