

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. DM22HO01748

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour:

A/C:

Sp. Reading

T/Radio:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

FBT 6408P 076/H New bike 16k.

Lowly Bill 80

21/10/22 2/5 \$1700 insured AH long (red 8563, 83%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/10/22-typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : TP

Lump Sum / L.B.H. (\$ 1700

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	761H
Vehicle Details	
Vehicle No.:	FB16408P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2022
Vehicle Make:	YAMAHA
Vehicle Model:	T150
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	G3P3E0002096
Chassis No.:	MH3UG131000002100
Maximum Power Output:	-
Open Market Value:	\$2,067.00
Original Registration Date:	19 Apr 2022
First Registration Date:	19 Apr 2022
Transfer Count:	1
Actual ARF Paid:	\$311.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$9,589.00
COE Rebate Amount:	\$9,218.00
Total Rebate Amount:	\$9,218.00

The information contained herein is correct as at 13 Oct 2022.

OK

INVOICE

Boltz PTE LTD
21 Woodlands Close
Pioneer Centre #16-24
Singapore 737854
Singapore
+65 8333 2635

2019296960

13014

2022

6690

Boltz PTE LTD
Raffles Place
+65 8333 2635
Angusmachan@boltz.com

Invoice Number: 22-1786
Invoice Date: October 7, 2022
Payment Due: October 7, 2022
Amount Due (SGD): \$0.00

Item	Quantity	Price	Amount
Q-1001	1	\$80.00	\$80.00
Bike Model: Yamaha Sniper 150 N-Reg Plate: FRT 6408 P PPS: 5-3L3B-0000 500010001 K-Reg: S157 Motor Vehicle S157 Motor Vehicle S157 Motor Vehicle			

Total: \$80.00

Payment on October 7, 2022 using a bank payment \$80.00

Amount Due (SGD) \$0.00

Vehicle is low risk. The Company accepts no responsibility for damages or others' misadventure to your vehicle while being towed.

3/10/22
Not Allowed
den
4/5 \$1700
4 days
take photos after rep.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE REPAIR ESTIMATE

Vehicle Registration No: FBT6408P

Date: 7 October 2022

Qty	Description	Condition	Repairer's Estimate
-----	-------------	-----------	---------------------

SPARE PARTS - LIST ITEMS

1	Front fender assy	90 Warped	cut/cr \$ 180.00 ✓
1	Front side cover LH	Warped	cr \$ 160.00 ✓
1	Front side cover RH	Warped	cr \$ 160.00 X
1	Front cowling assy	Warped	cr \$ 220.00 ✓
1	Front headlamp assy	380 Cracked	cr \$ 500.00 ✓
1	Front signal lamp LH	Cracked	cr \$ 120.00 ✓
1	Front pilot lamp LH	Cracked	cr \$ 120.00 ✓
1	Front fork assy LH	Bent	cr \$ 350.00 X
1	Front fork assy RH	Bent	cr \$ 350.00 X
1	Front side cover decal stickers	Necessary	cr \$ 80.00 ✓
1	side cover LH	Necessary	cr \$ 100.00 ✓
			\$ 2,340.00

SPECIAL NETT ITEMS

1	Front center compartment box	Warped	cr \$ 200.00 40 s/n
1	Rear storage top box	Scratched	cr \$ 300.00 250 s/n
			\$ 500.00
Total parts			\$ 2,840.00

front footrest LH cut \$ 48 ✓
front view mirror LH scr \$ 50 ✓
handle bar end LH cut \$ 30 ✓
fairing inner cover cr \$ 165 ✓
front stem bracket scr \$ 160 ✓

Vehicle Registration No: FBT6408P

Date: 7 October 2022

Total cost of parts c/f

\$ 2,840.00

S/No	Description	Repairer's Estimate
------	-------------	---------------------

LABOUR

1	To putty and spray painting the affected areas. Job Allowance.	11 \$ 1,600.00 X
2	To check front lighting and wiring.	11 \$ 100.00 X
3	To remove and install garnish and trim to facilitate the repair.	11 \$ 120.00 X
4	To apply anti rust proofing to the affected areas.	11 \$ 300.00 X
5	To remove and install front fender assy	11 \$ 180.00 X
6	To remove and install front side cover assy	11 \$ 180.00 X
7	To remove and install front signal lamp.	11 \$ 180.00 X
8	To remove and install front center compartment box	11 \$ 180.00 X
9	To remove and install front fork assy.	\$ 180.00 80
10	To remove and install front cowling assy.	11 \$ 180.00 X
11	To remove and install rear storage top box.	11 \$ 180.00 X
12	labour charge for replaced parts	\$ 400.00 260
13	To conduct chassis alignment.	11 \$ 350.00 X

Grand Total:

\$ 6,970.00

10,263

7-1723
102
7550.7
290
340
21807
202
1744