

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 14 Oct 2022

Preliminary Advice

Vehicle No	: SMK2100U	Accident Date	: 10/10/2022
Make	: BMW 520I	Policy No.	: DMPCSNW00080292201
Assignment Date	: 13/10/2022	Excess	: S\$950.00
Date of Inspection	: 13/10/2022	Est. Duration of Repair	: 8
Inspection At	: PERFORMANCE MOTORS LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,523.35
Revised Amount	:S\$	13,969.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,969.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	181,000.00
COE / PARF Rebate	:S\$	73,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107,356.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : lease note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .