

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63622
Date Estimated : 11/10/2022
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Chua Jian Construction Pte. Ltd.
10 Jalan Besar
#10-04 Sim Lim Tower
Singapore 208787

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK2100U	WBAJA12010BJ21285	29/03/2019	520i	32966

DESCRIPTION	VALUE
To replace left front fender, left front door, left rear door, left side skirting and make good rear left fender and rear bumper.	2975 / 2559 8,500.00
To respray left front fender, left front door, left rear door, left rear fender, rear bumper and left side skirting.	4293 5,404.00
To carry out body cavity preservation. (Per panel).	336 354.00
To check electrical wiring	168 177.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (2 doors).	1009 1,062.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	524 531.00
To replace tyre and wheel rim including balancing. (1x).	94.00
Sundries.	150.00

Total Labour 1: 16,272.00

DESCRIPTION	QTY	PRIC	VALUE
LIGHT ALLOY RIM 8JX18 W SPK 632	1	1,045.30	1,045.30
FRT LH DOOR ALUMINIUM	1	1,910.15	1,910.15
REAR LH DOOR ALUMINIUM	1	1,910.15	1,910.15
FRT LH SIDE PANEL ALUMINIUM	1	952.05	952.05
LH SILL TRIM PRIMED	1	433.70	433.70

Total Parts : 6,251.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motortrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 63622
Date Estimated : 11/10/2022
Prepared By : Jack Ng Guo Ming

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK2100U	WBAJA12010BJ21285	29/03/2019	520i	32966

Steve CLKK)
13/9/22, 4.40pm

00-11/11L
Excess-?
P/P
by RL y
8 d/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	16,272.00
Parts	:	6,251.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,576.63
Grand Total	:	24,099.98

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **