

ASS. R=UBI. *10/10/10*

REF: *CS/46122010163/Tay 3*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / *TP* / WS / TP RES / OD RES / EVA / INV / MV

To Insp. ed Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *463k*

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SL08712M* Yr Regn: *2016 / June*

Type: *M* Car / *M* Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Nissan X-trail* 2.0 c.c. *1997*

Colour: *117161* A/C: Insured / Std / NI / NA

Sp. Reading: *Blue* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JN1JANT 32Z 000 215*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Good* / Jammed / Leaked / Burnt or

Brake: *Good* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: *225 / 60 R18*

R: *1*

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / *PIR* / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. D.O.I. *13/10/22*

Survey held at *Prompt Auto*

Des. of Damages *Front* / *Rear* / *O/S* / *N/S* / *W/C* / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Rep. Form: _____

Lump Sum / L.S. / _____

Prompt Auto Solutions Pte Ltd

8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)

Tel: 97319322 - ROY CHAK

E-mail: promptautosolutions@gmail.com

REPAIR ESTIMATE

TO :	DATE :
ATTENTION :	JOB TYPE : THIRD PARTY
VEHICLE DETAILS	
VEHICLE NO: SLD8712M	DATE :
MAKE / MODEL: Nissan X-Trail	TIME :
CHASSIS NO: JN1JANT32Z0002145	
ACCIDENT DETAILS	

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Rear bumper	1	\$ 749.00	\$ de 749.00
2	Rear bumper centre cover	1	\$ 86.00	\$ de 86.00
3	Rear bumper RH reflector	1	\$ 112.00	\$ x un 112.00
4	Rear bumper LH reflector	1	\$ 112.00	\$ x un 112.00
5	Rear bumper RH side bracket	1	\$ 4.00	\$ de 43.00
6	Rear bumper LH side bracket	1	\$ 43.00	\$ de 43.00
7	Rear bumper reinforcement	1	\$ 598.00	\$ 3 ht 598.00
8	Rear bumper RH stay	1	\$ 197.00	\$ 2 un 197.00
9	Rear bumper LH stay	1	\$ 197.00	\$ 2 un 197.00
10	Rear bumper towing cover	1	\$ 118.00	\$ x un 118.00
11	Tailgate	1	\$ 5,201.00	\$ cu 5,201.00
12	Tailgate chrome moulding	1	\$ 156.00	\$ x un 156.00
13	Tailgate centre emblem	1	\$ 79.00	\$ x un 70.00
14	Tailgate "X-Trail" emblem	1	\$ 119.00	\$ un 119.00
15	Tailgate windscreen glass rubber moulding	1	\$ 98.00	\$ un 98.00
16	Tailgate lock	1	\$ 663.00	\$ x un 663.00
17	Tailgate weatherstrip	1	\$ 156.00	\$ 2 un 156.00
18	Tailgate RH electronic absorber damper	1	\$ 1,156.00	\$ x 1,156.00
19	Tailgate LH electronic absorber damper	1	\$ 1,156.00	\$ x 1,156.00
20	Tailgate RH touch sensor rubber seal	1	\$ 378.00	\$ x 378.00
21	Tailgate LH touch sensor rubber seal	1	\$ 378.00	\$ x 378.00
22	Tailgate lock	1	\$ 623.00	\$ x 623.00
23	Tailgate lock catch	1	\$ 44.00	\$ x 44.00
24	Tailgate inner trim board	1	\$ 46.00	\$ x un 46.00
25	Tailgate RH lamp	1	\$ 456.00	\$ x 456.00
26	Tailgate LH lamp	1	\$ 456.00	\$ x 456.00
27	Tailgate reverse camera	1	\$ 1,051.00	\$ x 1,051.00
28	RH taillamp	1	\$ 556.00	\$ x 556.00
29	LH taillamp	1	\$ 556.00	\$ x 556.00
30	Rear RH fender arch moulding	1	\$ 167.00	\$ x 167.00
31	Rear LH fender arch moulding	1	\$ 167.00	\$ x 167.00
32	End panel	1	\$ 485.00	\$ x 485.00
33	End panel inner garnish	1	\$ 78.00	\$ x un 78.00
34	End panel antenna sensor	1	\$ 133.00	\$ x un 133.00
35	Rear RH fender inner trim board	1	\$ 505.00	\$ x un 505.00
36	Rear LH fender inner trim board	1	\$ 505.00	\$ x un 505.00

37	Rear floor panael carpet cover	1	\$ 167.00	\$ X 167.00
38	Rear floor panel cover board	1	\$ 959.00	\$ X 959.00
39	Exhaust silencer	1	\$ 784.00	\$ X 784.00
40	Exhaust silencer gasket	1	\$ 55.00	\$ X 55.00
41	Bonnet	1	\$ 1,021.00	\$ bt 1,021.00
42	Bonnet RH hinge	1	\$ 114.00	\$ X un 114.00
43	Bonnet LH hinge	1	\$ 114.00	\$ X un 114.00
44	Bonnet lock	1	\$ 98.00	\$ X un 98.00
45	Bonnet inner rubber seal	1	\$ 34.60	\$ X un 69.20
46	Bonnet insulator	1	\$ 202.00	\$ X un 202.00
47	Front bumper	1	\$ 598.00	\$ de 598.00
48	Front bumper chrome moulding	1	\$ 171.00	\$ aut 171.00
49	Front bumper RH fog lamp cover	1	\$ 88.00	\$ X un 88.00
50	Front bumper RH fog lamp	1	\$ 303.00	\$ X un 303.00
51	Front bumper LH fog lamp cover	1	\$ 88.00	\$ X un 88.00
52	Front bumper LH fog lamp	1	\$ 303.00	\$ con 303.00
53	Front bumper lower grille	1	\$ 224.00	\$ cut 224.00
54	Front bumper inner bracket	1	\$ 645.00	\$ X un 645.00
55	Front bumper inner sponge	1	\$ 335.00	\$ int 335.00
56	Front bumper reinforcement	1	\$ 527.00	\$ bt 527.00
57	Front bumper reinforcement RH stay	1	\$ 98.00	\$ X un 98.00
58	Front bumper reinforcement LH stay	1	\$ 98.00	\$ X un 98.00
59	Front bumper RH retainer	1	\$ 32.00	\$ de 32.00
60	Front bumper LH retainer	1	\$ 32.00	\$ de 32.00
61	Front bumper under cover	1	\$ 178.00	\$ X un 178.00
62	Front grille	1	\$ 423.00	\$ cut 423.00
63	Front grille emblem	1	\$ 45.00	\$ re 45.00
64	RH headlamp assy	1	\$ 2,518.00	\$ con 2,518.00
65	LH headlamp assy	1	\$ 2,518.00	\$ cut 2,518.00
66	Front RH fender arch moulding	1	\$ 181.00	\$ X 181.00
67	Front LH fender arch moulding	1	\$ 181.00	\$ X un 181.00
68	Support panel "centre"	1	\$ 167.00	\$ X 167.00
69	Support panel "RH side"	1	\$ 708.00	\$ X 708.00
70	Support panel "LH side"	1	\$ 708.00	\$ X 708.00
71	Aircon condenser	1	\$ 783.00	\$ X 783.00
72	Radiator assy	1	\$ 713.00	\$ X 713.00
73	Oil cooler	1	\$ 563.00	\$ X 563.00
74	Air duct	1	\$ 143.00	\$ X 143.00

TOTAL PRICE: \$ 34,568.20
 LIST LESS 10%: \$ 3,456.82
 SUB TOTAL PRICE: \$ 31,111.38

S/N	DESCRIPTIONS	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Rear bumper clips	1set	\$ 70.00	\$ 3 one 70.00
2	Rear bumper reverse sensor (4 sensors)	1set	\$ 480.00	\$ un 480.00
3	Tailgate windscreen glass sealant	1	\$ 70.00	\$ 62 - 50 70.00
4	Tailgate windscreen glass inner seal	1	\$ 50.00	\$ de 40 50.00
5	End panel seal	1	\$ 60.00	\$ 7 40 60.00
6	End panel inner garnish clips	1set	\$ 50.00	\$ 7 30 50.00

7	Rear RH fender inner trim board clips	1set	\$ 70.00	\$ X NN 70.00
8	Rear LH fender inner trim board clips	1set	\$ 70.00	\$ X NN 70.00
9	Front bumper clips	1set	\$ 70.00	\$ 30 me 70.00
10	Front number plate	1	\$ 70.00	\$ Mt-45 70.00
11	Bonnet insulator clips	1set	\$ 70.00	\$ X NN 70.00
12	Radiator coolant	1	\$ 80.00	\$ X NN 80.00

S/N TOTAL PRICE: \$ 1,210.00

S/N	DESCRIPTIONS			PRICE
	(Rear portion)			
1	Labour charges on affected areas and replaced parts as listed			\$ 700 1,400.00
2	Re-spray affected areas and parts			\$ 700 1,200.00
3	Check wiring and lighting system			\$ 30 80.00
4	Apply anti rust chemical coating			\$ 30 80.00
5	Remove and refit tailgate windscreen glass			\$ 120 220.00
6	Remove, replace and adjust tailgate reverse camera			\$ 30 100.00
7	Remove and replace tailgate inner parts to new tailgate			\$ 60 150.00
8	Remove and replace rear bumper reverse sensors			\$ 30 80.00
9	Remove and replace rear inner trims and garnish			\$ 60 280.00
10	Remove and replace exhaust silencer and gasket			\$ X NN 180.00
	(front portion)			
11	Labour charges on affected areas and replaced parts as listed			\$ 500 1,200.00
12	Re-spray affected areas and parts			\$ 500 1,200.00
13	Check wiring and lighting system			\$ 30 70.00
14	Apply anti rust chemical coating			\$ 30 60.00
15	Remove and replace aircon condenser and pipes			\$ X NN 200.00
16	Remove and replace radiator assy and hoses			\$ X NN 200.00
17	Remove and replace oil cooler and brackets			\$ X NN 150.00
18	Refocus and adjust headlamps assy			\$ 40 80.00

