



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22010165/Uvy3m4	
			Date: 19/10/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6518K	Veh. Inspected	SFU 1228Y	
Policy No.	D-19094111MFB	Coverage (\$)	0.00	
Claim No.	D22003222MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	13/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WVWZZZAUZKW019452	Colour	GREY	
Odometer	103858 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2022	Inspection Date	14/10/2022	
Survey held at	SM SPRAY PAINTING NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	