

FBT7414P. 2022 May.
Honda ADV150. 1H9CC
MH1KF6119MK042916

TIP China
Celina.

Rees Number Plate.	Best	20(SN)	✓
Rees Mudflap.	Delnd	189.	✓
Rees Mudflap Reflector	HP m	25	+
Rees Signal Lamp x 02	HP m	60x2 = 120.	+
Rees Exhaust Protector (Rees).	Cut	95	✓
Rees Exhaust Heat Shield.	HP m	128	+
Rees Exhaust Pipe.	HP m	860	+
Rees Brake Caliper.	Delnd	287	✓
Rees Box	Cut	380(SN) 280(SN)	
Rees Box Bracket x 02.	HP m	180(SN).	+
Rees Engine Casing.	Cut	268	✓
Rees Engine Casing Lower Garnish.	Cut	245.	✓

FBT7414P.

Reer LH Foot Rest.

Cut 48

Front LH Foot Rest Board

Cut 369

Front LH Foot Rest Board Outer Garish.

Cut 128

Balancer Ltl.

Cut 30

Handle Lever LH.

52

Front LH Wing Mirror

} Cut

65

Front LH Signal Lamp.

Broken 85

Front LH Bowling.

Cut 226

Handlup

could

855

Handlup Bracket.

==

Front Fork Assy

} HP
or

680. +

Fork Underbracket.

220. +

Steering Cone and Bearing.

120. X

HP
new

FBT7414P.

Labour.

Spray Painting.

Wiring.

~~400~~ 250.

~~400~~ 200

~~50~~ 30

list: 2942

len 10%: 2647.80

S.N: 300

labour: 400

total: 3427.80

4/51 2.7K. ✓
04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: