

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 07 Feb 2023

Preliminary Advice

Insured Vehicle No	: SFP9999D	Accident Date	: 11/10/2022
TP Vehicle No	: FBT7414P	Assignment Date	: 13/10/2022
Make	: HONDA ADV150	Est. Duration of Repair	: 04
Date of Inspection	: 25/10/2022		
Inspection At	: JEC AUTO SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,525.00
Revised Amount	:S\$	3,427.80
Check Items (Estimated)	:S\$	
Total	:S\$	3,427.80
Lump Sum Repair	:S\$	2,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a "Without Prejudice" basis.
- Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.