

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010167/KVY3Q2**Date:** 30/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00085812200

Claimant Vehicle No : FBP7930L**Insured Vehicle No :** SJW5109Z

Date of Loss: 09/10/2022

Nature of Claim: TP

Claim No: SNM22D207252/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBP7930L**

Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS

Engine No: G3J8E0090171

Reg. Date: 14/06/2019 (Man. Year: 2019)

Chassis No: MH3SG4640KJ049876

Colour: Red/Grey

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	120/70 R14
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,265.00	3,587.10	3,677.90	50.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	690.00	365.00	325.00	47.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,955.00	3,952.10	4,002.90	50.32
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	7,955.00	3,100.00	4,855.00	61.03

INSPECTION

Date of Assignment: 13/10/2022

Date Inspected: 14/10/2022 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
#01-21
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2022)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP7930L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HADLE BAR	Bent	165.00 FL	*145.00 FL
2	1		*SET BALANCER	O/S Dented	120.00 FL	*60.00 FL
3	1		*SET MIRROR	O/S Cut	140.00 FL	*70.00 FL
4	1		*BRAKE LEVER	Dented	75.00 FL	*75.00 FL
5	1		*FRONT V PANEL	Mtg Cracked	180.00 FL	*180.00 FL
6	1		*HEAD LAMP ASSY	Broken	550.00 FL	*499.00 FL
7	1		*SET SIGNAL LIGHT L/RH	Serviceable	150.00 FL	*- FL
8	1		*FRONT MUDGUARD	Repair	250.00 FL	*- FL
9	1		*FRONT RH PANEL	Mtg Cracked	180.00 FL	*180.00 FL
10	1		*FRONT LH PANEL	Mtg Cracked	180.00 FL	*180.00 FL
11	1		*HEAD LAMP LOWER GUARD	Cracked	220.00 FL	*220.00 FL
12	1		*SET FORK TUBE	Bent	550.00 FL	*550.00 FL
13	1		*SET FORK BRACKET	Distorted	280.00 FL	*280.00 FL
14	1		*CENTRE LEG SHIELD	Cracked	180.00 FL	*180.00 FL
15	1		*RH LEG SHIELD	Serviceable	180.00 FL	*- FL
16	1		*FRONT LOWER PANEL RH	Cut	190.00 FL	*190.00 FL
17	1		*REAR TAIL PANEL -RH	Repair	220.00 FL	*- FL
18	1		*EXHAUST GUARD	Dented / Cut	150.00 FL	*150.00 FL
19	1		*EXHAUST PIPE	Repair	1,350.00 FL	*- FL
20	1		*DASH BOARD PANEL	Mtg Cracked	180.00 FL	*180.00 FL
21	1		*DASH BOARD LID	Cracked	280.00 FL	*220.00 FL
22	1		*RH CENTRE V PANEL	Mtg Cracked	180.00 FL	*180.00 FL
23	1		*FRONT RIM	Serviceable	350.00 FL	*- FL
24	1		*BRAKE DISC	Serviceable	320.00 FL	*- FL
25	1		*REAR BOX	Serviceable	320.00 FS	*- FS
26	1		*BODY DECAL STICKER	Necessary	150.00 FS	*150.00 FS
27	1		*BOARD FOOTREST L/RH	O/S Cut	280.00 FL	*140.00 FL
28	1		*MOLE SIDE COVER L/RH	O/S Dented	280.00 FL	*140.00 FL
29	1		*BODY CENTRE PANEL	Repeated	190.00 FL	*- FL
30	1		*RIGHT PANEL	Repeated	180.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,020.00	3,969.00
- List Item Discount on L Items 10.00/10.00% (\$)	755.00	381.90
Total Parts (\$)	7,265.00	3,587.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	35.00
2	REMOVE & REPLACE PARTS ,ALIGN & ETC	New	280.00	150.00
3	REMOVE & REPLACE FORK TUBE ,FORK OIL SEAL , & TOP UP FORK OIL	New	120.00	80.00
4	ALIGNMENT TO FRONTAL BODY	New	250.00	100.00
Gross Labour Cost (\$\$)			690.00	365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >