



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 2022 - 15

Date: 17th October 2022

Our Ref: CS1/SCD22010168/Eqy3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMX 7911U

INSURED VEHICLE: QX 1255Y

ACCIDENT DATE: 03/03/2022

We thank you for your instruction on 11/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMX 7911U from M/s AIG Asia Pacific Insurance Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SMX 7911U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMX 7911U
Make & Model	: Toyota Vios (E) 4-Door Sedan (Auto) (2WD)
Chassis Number	: MR2B23F3801215571
Year of Registration	: 2021
Engine Capacity	: 1496 cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$4,705.77 (before GST) quoted by M/s Borneo Motors (S) Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.

Vehicle Inspected By:

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMX 7911U

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	COVER FR BUMPER L/C	CRUSHED	525.30
10	PIECE RR BUMPER	NECESSARY	43.00
1	RETAINER FR BUMPER (NPA)	NOT NECESSARY	-
1	FENDER SUB-ASSY FR	DENTED	809.10
1	MIRROR ASSY OUTER R	BROKEN	1,335.50
	LESS 25% DISCOUNT		-678.23
			2,034.67
<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	30.00
			30.00
<u>LABOUR</u>			
	MERIMEN'S PROCESSING FEES.		11.00
	CHECK WIRING AND CONDUCT WATER TEST.		110.16
	TO RESET ECU AND REPROGRAMME.		162.00
	REPLACE ACC DAMAGED PARTS.		1,296.00
	RESPRAY ACC AFFECTED AREAS.		1,062.00
			2,641.16
GRAND TOTAL			4,705.83
RECOMMENDED COST OF REPAIRS			4,705.77

Report Ref No. CS1/SCD22010168/Eqy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.