



AIG Asia Pacific Insurance Pte. Ltd.

AIG Building
78 Shenton Way #07-16
Singapore 079120
T : (65) 6419 3000
www.aig.sg

Claim No: 5910199383SG **Date of Survey:** 04/03/2022
Repairer: BORNEO MOTORS (S) PTE LTD

REFERENCE

Insured: LU BAOJIAN **Policy No:** [REDACTED]
Date of Loss: 03/03/2022 **Nature of Claim:** OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SMX7911U
Make & Model: TOYOTA VIOS, 1.5 (A) **Reg. Date:** 29/01/2021
Engine No: 2NR5478962 **Chassis No:** MR2B23F3801215571

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No		
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes	Pre-accident Condition:	Good

COST OF CLAIMS

	Repairer's	Our Offer	Difference	Diff %
Parts	2,114.70	2,034.67	80.03	3.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.16	2,671.16	1,179.00	30.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,964.86	4,705.83	1,259.03	21.11
Approved Total (Overridden) (S\$)		4,705.77		
(S\$)	5,964.86	4,705.77	1,259.09	21.11
+ GST 7.00/7.00% (S\$)	417.54	329.40	88.14	21.11
Nett Amount (S\$)	6,382.40	5,035.17	1,347.23	21.11

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 5.0 days

Authorised Repair : Yes

Inspection conducted by : Ng, Thaddaeus-HC (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	S52119-YP913	*COVER FR BUMPER L/C	CRU	525.30 FL	*525.30 FL ✓
2	10	S52161-0K040	*PIECE RR BUMPER	NEC	43.00 FL	*43.00 FL ✓
3	1	S52536-0D230	*RETAINER FR BUMPER		106.70 FL	Reuse X NN
4	1	S53802-0D100	*FENDER SUB-ASSY FR	DD	809.10 FL	*809.10 FL ✓
5	1	S87940-0D740	*MIRROR ASSY OUTER R	BR	1,335.50 FL	*1,335.50 FL ✓
					Sub Total (\$\$)	2,819.60 2,712.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	704.90 678.23
					Total Parts (\$\$)	2,114.70 2,034.67

F=Franchise part. L=ListItemDisc.

AIG Asia Pacific Insurance Pte. Ltd./SMX7911U/11/03/2022 15:20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRIES	New	30.00	30.00 ✓
2	MERIMEN'S PROCESSING FEES	New	11.00	11.00 ✓
3	CHECK WIRING AND CONDUCT WATER TEST	New	110.16	110.16 ✓
4	TO RESET ECU AND REPROGRAMME	New	162.00	162.00 ✓
5	REPLACE ACC DAMAGED PARTS	New	1,944.00	1,296.00 ✓
6	RESPRAY ACC AFFECTED AREAS	New	1,593.00	1,062.00 ✓
Gross Labour Cost (\$\$)			3,850.16	2,671.16

AIG Asia Pacific Insurance Pte. Ltd./SMX7911U/11/03/2022 15:20

< END OF REPORT >