

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 07 Dec 2022

**Preliminary Advice**

|                    |                                                                                                            |                         |              |
|--------------------|------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBE7205E                                                                                                 | Accident Date           | : 08/10/2022 |
| TP Vehicle No      | : SMQ1722A                                                                                                 | Assignment Date         | : 13/10/2022 |
| Make               | : TOYOTA VIOS                                                                                              | Est. Duration of Repair | : 2          |
| Date of Inspection | : 17/10/2022                                                                                               |                         |              |
| Inspection At      | : AH LIM MOTOR COMPANY (AMK)<br>10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT<br>SINGAPORE 568047 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 8,159.47 |
| Revised Amount              | :S\$ | 2,473.73 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,473.73 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.