

ASS. REC. BY:

REF:

CAZ/ 22010169/Kny3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMQ 1722A

Yr Regn:

10.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

c.c

1496

Colour

M. White

A/C:

Insured / Std / NI / NA

Sp. Reading

49629

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B2 31-3401190474

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

8/10/22

D.O.A.

17/10/2022

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/12 82473.73 Car

(red, \$5685.74, 70%)

Date/Time, File Pass to?

1) 07/12/22

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

TP-CTI

Lump Sum / I.B.I. (\$) 2473.73

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	093B

Vehicle Details

Vehicle No.:	SMQ1722A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 G (AUTO)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	2NR5396661
Chassis No.:	MR2B23F3401190474
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,572.00
Original Registration Date:	18 Oct 2019
First Registration Date:	18 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$15,572.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Oct 2029
PARF Rebate Amount:	\$11,679.00

Intended COE Rebate Details

COE Expiry Date:	17 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$23,864.00
Total Rebate Amount:	\$35,543.00

The information contained herein is correct as at 10 Oct 2022

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIANG YING
 138B TOA PAYOH LOR 1A
 #17-22
 SINGAPORE 312138
TEL: 81133311
ATTN:

Estimate No: MC1903048
Date: 11 Oct 2022
Policy No: P10262095R02
Veh Reg No: SMQ1722A
Make/Model: TOYOTA VIOS 1.5 G
 AUTO

Your Ref No: SMQ1722A
Claim Type: Third Party
Accident Date: 08/10/2022
TP Veh Reg No: GBE7205E

19m
LCIC
Not Authorised
Repair After Paint
2473-73 2days

Estimate Repair Cost to Vehicle No :SMQ1722A

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 RADIATOR GRILLE BASE	1 PC	Sm 254.50	<i>2</i>
2 RADIATOR GRILLE EMBLEM	1 PC	Sm 61.90	<i>2</i>
3 RADIATOR GRILLE EMBLEM COVER	1 PC	Sm 105.40	<i>2</i>
4 RADIATOR GRILLE MLDG LH & RH	2 PC	Sm 146.80	<i>X</i>
5 RADIATOR GRILLE TOP RUBBER	1 PC	Sm 25.50	<i>X</i>
6 RADIATOR GRILLE CTR BUSH	1 PC	Sm 20.90	<i>X</i>
7 FRONT BUMPER	1 PC	cm 525.80	<i>2</i>
8 FRONT BUMPER CLIPS	4 PC	na 19.20	<i>2</i>
9 FRONT BUMPER CTR GRILLE	1 PC	cm Sm 96.60	<i>X</i>
10 FRONT BUMPER LOWER GRILLE	1 PC	na 387.30	<i>1</i>
11 FRONT BUMPER LOWER GRILLE LAMP LH & RH	2 PC	Sm 1,383.20	<i>X</i>
12 FRONT BUMPER LOWER GILLE LAMP CLIPS	4 PC	na 15.56	<i>X</i>
13 FRONT BUMPER LOWER GRILLE TOW COVER	1 PC	Sm 96.60	<i>X</i>
14 FRONT BUMPER REINFORCEMENT	1 PC	na 423.90	<i>X</i>
15 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	Sm 213.40	<i>X</i>
16 HEADLAMP LH & RH	2 PC	Sm 3,337.60	<i>X</i>
17 FOGLAMP COVER LH & RH	2 PC	Sm 187.00	<i>X</i>
18 AIR GUIDE TOP LH & RH	cm 2 PC	169.40	<i>X</i>
19 AIR GUIDE BTM LH & RH	cm 2 PC	136.80	<i>X</i>
20 AIR GUIDE CLIPS	2 PC	na 8.20	<i>X</i>
21 RADIATOR SUPPORT PANEL TOP COVER	1 PC	Sm 290.40	<i>X</i>
22 RADIATOR SUPPORT PANEL TOP COVER CLIPS	8 PC	na 33.60	<i>X</i>
23 FRONT FENDER COWLING CLIPS	16 PC	na 43.20	<i>X</i>
		7,982.76	
	Less 25%	1,995.69	5,987.07
Special Nett			
24 NUMBER PLATE	1 PC	cm 35.00	<i>1</i>
		35.00	35.00
LABOUR			
25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>201</i>
26 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	na 60.00	<i>X</i>
27 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT BONNET INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>1801</i>

Zia
 Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIANG YING
138B TOA PAYOH LOR 1A
#17-22
SINGAPORE 312138
TEL: 81133311
ATTN:

Estimate No: MC1903048
Date: 11 Oct 2022
Policy No: P10262095R02
Veh Reg No: SMQ1722A
Make/Model: TOYOTA VIOS 1.5 G
AUTO

Your Ref No: SMQ1722A
Claim Type: Third Party
Accident Date: 08/10/2022
TP Veh Reg No: GBE7205E

Estimate Repair Cost to Vehicle No :SMQ1722A

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
28 TO SPRAY FRONT BONNET,FRONT BUMPER.	1 PC	500.00	200
		1,100.00	1,100.00
		Total	SS 7,122.07
		Add GST @ 7%	498.54
		Total Amount Payable	SS 7,620.61

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED TWENTY AND CENTS SIXTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

8159.47.

For AH LIM MOTOR COMPANY


Ah Lim Motor Company

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIANG YING
138B TOA PAYOH LOR 1A
#17-22
SINGAPORE 312138
TEL: 81133311
ATTN:

Estimate No: MC1903048
Date: 17 Nov 2022
Policy No: P10262095R02
Veh Reg No: SMQ1722A
Make/Model: TOYOTA VIOS 1.5 G
AUTO

Your Ref No: SMQ1722A
Claim Type: Third Party
Accident Date: 08/10/2022
TP Veh Reg No: GBE7205E

10/18

NR 2B 23F 3401190474

Estimate Repair Cost to Vehicle No :SMQ1722A

Description	Quantity	List Price	Amount
		S\$	S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 DAYLIGHT LED LAMP LH & RH	2 PC	1,383.20	1,383.20
		1,383.20	1,383.20
		Total	S\$ 1,383.20
		GST Amount	S\$ 96.82
		Total Amount Payable	S\$ 1,480.02

The above vehicle was surveyed by KENNETH KONG -LKK on 17/10/2022

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE