



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302814

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/05/2023
Reference CC3/CTI22010171/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3837Y
Insured Veh. SLJ 5965M
Claim No. SNM22D206948/C02
Policy No. DMPCSNW00120142201
Accident Date 28/09/2022
Inspection Date 29/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22010171/Tpa3q2 Date: 05/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 5965M	Veh. Inspected	SHC 3837Y	
Policy No.	DMPCSNW00120142201	Coverage (\$)	0.00	
Claim No.	SNM22D206948/C02	Excess (\$)	0.00	
Assign From		Assign Date	29/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU603089103	Colour	BLUE	
Odometer	332603 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2022	Inspection Date	29/09/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3837Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	503.04	503.04
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER COVER	DEFORMED	654.96	654.96
1	REAR BUMPER UNDER SIDE CENTRE COVER	NOT NECESSARY	654.96	-
1	COVER FLOOR UNDER NO2	NOT NECESSARY	220.50	-
2	REAR BUMPER UNDER SIDE COVER LH RH @\$232.00	NOT NECESSARY	462.00	-
1	REAR BUMPER TOWING COVER	DEFORMED	82.70	82.70
2	REAR BUMPER SIDE RETAINER LH RH @\$112.70	NOT NECESSARY	225.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	378.32	-
2	REAR BUMPER ARM ASSY LH RH @\$139.60	NOT NECESSARY	279.20	-
1	REAR END PANEL	NOT NECESSARY	738.96	-
1	REAR END PANEL GARNISH	NOT NECESSARY	165.80	-
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
2	REAR BUMPER REFLECTOR LH RH @\$55.00	NOT NECESSARY	110.00	-
1	BACK DOOR GARNISH SUB ASSY	TO REPAIR SEE LABOUR	1,054.71	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NOT NECESSARY	81.43	-
1	REAR WINDSCREEN GLASS WITH MOULDING	NOT NECESSARY	1,884.32	-
1	REAR TRUNK LID COVER	TO REPAIR SEE LABOUR	1,303.29	-
1	REAR TRUNK LID GLASS	NOT NECESSARY	1,569.70	-
1	REAR EXHAUST PIPE CENTRE INSULATOR	NOT NECESSARY	498.60	-
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,163.40	-
	LESS 25% DISCOUNT		-3,200.17	-346.75
			9,600.50	1,040.23
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00

Report Ref No. CC3/CTI22010171/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	NOT NECESSARY	55.00	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
			340.70	285.70
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BACK DOOR GARNISH SUB ASSY AND REAR TRUNK LID COVER .		1,200.00	525.00
	SPRAY PAINTING CHARGE.		850.00	600.00
	TOWING FEE		60.00	60.00
	CHECK ALL LIGHTING .		60.00	30.00
	TUFF KOTE.		80.00	30.00
	REMOVE/REFIX EXHAUST PIPE .	NOT NECESSARY	150.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
			2,580.00	1,395.00
GRAND TOTAL			12,521.20	2,720.93

RECOMMENDED COST OF REPAIRS			2,720.93
------------------------------------	--	--	-----------------

Report Ref No. CC3/CTI22010171/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3837Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3837Y

RE-INSPECTION

