

CTI.

705-12

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC3837Y

Make : Toyota

Model : Prius (G4A)

Date: 29/09/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER			\$ 503.04	4
10	REAR BUMPER CLIPS			\$ 22.00	4
1	REAR BUMPER LOWER COVER			\$ 654.96	4
1	REAR BUMPER UNDER SIDE CENTRE COVER			\$ 654.96	?
1	COVER FLOOR UNDER NO2			\$ 220.50	?
1	REAR BUMPER UNDER SIDE COVER LH RH		\$ 232.00	\$ 462.00	?
1	REAR BUMPER TOWING COVER			\$ 82.70	4
2	REAR BUMPER SIDE RETAINER LH RH		\$ 112.70	\$ 225.40	x
1	REAR BUMPER REINFORCEMENT			\$ 378.32	?
2	REAR BUMPER ARM ASSY LH RH		\$ 139.60	\$ 279.20	?
1	REAR END PANEL			\$ 738.96	x
1	REAR END PANEL GARNISH			\$ 165.80	x
1	REAR WIRING ASSY			\$ 582.40	?
2	REAR BUMPER REFLECTOR LH RH		\$ 55.00	\$ 110.00	x
1	BACK DOOR GARNISH SUB ASSY			\$ 1,054.71	Rx
1	REAR TRUNK LID LOGO (PRIUS)			\$ 62.14	4
1	REAR TRUNK LID LOGO (HYBRID)			\$ 62.14	4
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$ 81.43	x
1	REAR WINDSCREEN GLASS WITH MOULDING			\$ 1,884.32	x
1	REAR TRUNK LID COVER			\$ 1,303.29	Rx
1	REAR TRUNK LID GLASS			\$ 1,569.70	x
1	REAR EXHAUST PIPE CENTRE INSULATOR			\$ 498.60	x
1	REAR EXHAUST PIPE HANGER			\$ 40.70	x
1	REAR EXHAUST PIPE			\$ 1,163.40	x
	SUB TOTAL			\$ 12,800.67	
	LESS 25%			\$ 3,200.17	
	DISCOUNTED TOTAL			\$ 9,600.50	
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$ 60.00	Nett
1	REAR TRUNK LID APPS STICKER			\$ 40.00	Nett
1	REAR NUMBER PLATE WITH TRIM COVER			\$ 55.00	Nett
1	REAR BUMPER RUBBER MAT			\$ 50.00	Nett
1	REAR REVERSE SENSOR			\$ 135.70	Nett
				\$ 340.70	Nett
	Labour Charge				
	PANEL BEATING			\$ 1,200.00	
	SPRAY PAINTING CHARGE			\$ 850.00	
	TOWING FEE			\$ 60.00	
	CHECK ALL LIGHTING			\$ 60.00	
	TUFF KOTE			\$ 80.00	
	REMOVE/ REFIX EXHAUST PIPE			\$ 150.00	
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$ 120.00	
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00	
	TOTAL LABOUR			\$ 2,580.00	

Qty	Parts Description / Labour	Type	Unit Price	Amount
	ESTIMATE TOTAL			\$ 12,521.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpuk 97495749
 WP 29/9/22 2415pm
 9/9 Resurvey before paint
 Tanpuk 97495749
 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Date/Time: 29.09.2022 12:43

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4922217

JC NO 805531721


CUSTOMER		REGN NO: SHC3837Y	MILEAGE
IR/MS COMFORT TRANSPORTATION PTE LTD		MAKE: TOYOTA	FUEL
CUSTOMER NO. 7010045		MODEL PRIUS HYBRID(G4A28.09.2022 19:35	E.....1/2.....
ADDRESS 383 SIN MING DRIVE		YR OF MANU. 05.12.2019	DATE/TIME IN
Singapore SINGAPORE 575717		CHASSIS CODE JTDKB3FU603089103	TARGET DATE
TEL. (R) 65508755 (O)		COMPLETION DATE/TIME:	
(P)			
DISCOUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 28.09.2022

Incident Nature: 3P 28.09.2022

Slip/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHC3837Y

YY

Vehicle No.:

SHC3837Y

Signature/Date

Signature/Date


Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: _____ Time Received: <u>2005</u>		3. Vehicle Type: ☐ Private ☐ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	
2. ☐ New ☐ SPARK Kakis Name of Customer: <u>MR Goh</u> Contact No.: <u>[REDACTED]</u> Vehicle No.: <u>83722819</u> Make / Model / Colour: <u>PRUIS</u> Email: _____		4. Type of Towing: ☐ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
7. Location: <u>6 FERNHILL RD</u>		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____		6. Parts Replaced/Remarks: _____ _____ _____	
10. Odometer Reading: _____ Fuel Level: ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested		 # : Cracked X : Dented / : Scatched O : Missing _____ Signature of Customer	
Job Attended 12. Tow Truck / Recovery Van: ☐ VRS ☐ QA ☒ GAO ☐ OTHERS Name of Driver: <u>KANG</u> Vehicle No.: <u>129237C</u> Time Dispatch: <u>2005</u> Time of Arrival: <u>2125</u> Time Completed: <u>2215</u>			
Cash Invoice Details (if applicable)			
13. Cash Invoice No.: _____			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
<u>28/9/02</u> Date		<u>2215</u> Time	
_____ Signature of Customer			
14. WORKSHOP			
_____ Name of Attending Staff/Guard		_____ Date & Time of Arrival	
_____ Signature of Attending Staff/Guard			