



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983		Ref: CS/ASM22010173/Aqy3 Date: 14/10/2022 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 564D	Veh. Inspected	SNC 3985G
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04C5P	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	13/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	02/10/2022	Inspection Date	14/10/2022
Survey held at	TK MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6, #02-56, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			