



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN: LOH CYNTHIA

Ref: CS/ASM22010173/Aqy3e2

Date: 28/02/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 564D	Veh. Inspected	SNC 3985G
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S2M04C5P	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	13/10/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 CAB	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2054402F465953	Colour	WHITE
Odometer	84810 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	MICHELIN	6 mm
L/H Front Tyre	225/40 R18	MICHELIN	6 mm
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2022	Inspection Date	14/10/2022
Survey held at	TK MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6, #02-56, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**