



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0878/2022/EQ  
DATE : 12-Oct-22  
WIP : 45359

*Xin Yu*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/2022

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ALI MUSLIM POTIA  
ADDRESS : 3 BLAIR ROAD  
SINGAPORE 089903  
  
TELEPHONE : HP +65 96470667  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900258717-02  
VEHICLE NO : **SJW 9803 B**  
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC  
MODEL YEAR : 30/12/2019  
ENGINE NO : CZD 886608  
CHASSIS NO : WAUZZZF31L1015542  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 8-Oct-22  
PLACE OF ACCIDENT : VIVO CITY CAR PARK B2



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 9803 B**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ <del>400.00</del> 250	
3	TO REMOVE AND REINSTALL FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>2,400.00</del> 1000	
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ <del>2,000.00</del> 1650	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 5,560.00</b>	

LHS Front Door ✓



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 9803 B**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✗
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,032.00</b>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 9803 B**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Distal</i>	1	\$	1,235.00 ✓	987.60
2	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$	66.00 ✗	
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$	242.00 +	
4	FRONT BUMPER GRILLE - LH <del>cut</del> <i>cut</i>	1	\$	124.00 ✗ ✓	98.80
5	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$	212.00 ✗ ✗	
6	FRONT BUMPER SPOILER <i>cut</i>	1	\$	426.00 ✓	340.80
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cut</i>	1	\$	171.00 ✓	136.40
8	RADIATOR GRILLE <i>new</i>	1	\$	1,594.00 +	
9	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$	271.00 +	
10	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$	114.00 +	
11	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$	974.00 +	
12	FRONT BUMPER TOP COVER <i>new</i>	1	\$	137.00 +	
13	FRONT BUMPER GUIDE SECTION - LH <i>end</i>	1	\$	43.00 ✓	34.24
14	AIR CONDITIONER STICKER <i>new</i>	1	\$	9.00 +	
15	CAUTION SIGN STICKER	1	\$	16.00 +	
16	HORN HIGH TONE - LH <i>new</i>	1	\$	154.00 +	
17	HORN BRACKET - LH <i>new</i>	1	\$	25.00 +	
18	FRONT PARKING AID SENSOR <i>new</i>	1	\$	266.00 ✗ ✗	
19	FRONT PARKING AID SEAL RING <i>new</i>	4	\$	10.00 +	
20	FRONT FENDER - LH <i>Distal</i>	1	\$	1,445.00 ✓	1,156.00
<b>SUB TOTAL SPARE PARTS</b>				<b>\$ 7,534.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 9803 B**

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 66.00	+
22	FRONT FENDER BRACE - LH <i>Best</i>	1	\$ 98.00	? ✓ 77.68
23	FRONT FENDER BRACKET - LH <i>And</i>	1	\$ 39.00	? ✓ 30.48
24	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 260.00	+
25	FRONT WHEEL HOUSING LINER COVER - LH <i>new</i>	1	\$ 18.00	+
26	HEADLIGHT MOUNTING - LH / RH <i>new</i>	2	\$ 264.00	+
27	HEADLIGHT - LH <i>cracked</i>	1	\$ 5,952.00	✓ 4,761.60
28	HEADLIGHT POWER MODULE <i>new</i>	1	\$ 850.00	+
29	HEADLIGHT HEAT SINK <i>new</i>	1	\$ 870.00	+
30	HEADLIGHT HOSE - LH <i>new</i>	1	\$ 28.00	+
31	LIFT CYLINDER - LH <i>And</i>	1	\$ 231.00	✓ 184.40
32	LIFT CYLINDER HOSE <i>new</i>	1	\$ 92.00	+
33	LIFT CYLINDER WASH WATER RESERVOIR <i>new</i>	1	\$ 240.00	?
34	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 43.00	+
35	RADIATOR AIR GUIDE - UPPER / LOWER <i>new</i>	2	\$ 96.00	+
36	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 566.00	✓ 452.00
37	FRONT ALUMINIUM RIM <i>new</i>	1	\$ 1,750.00	+
38	FRONT ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	+
39	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	+
40	SUNDRIES <i>new</i>		\$ 500.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 19,561.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,032.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 25,593.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*  
SURVEYED DATE : *13/10/22*  
AUTHORISED DATE :  
EXCESS COST : *7 days*  
LIABILITY :  
REMARKS : *Not Authorised, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT