

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0876/2022/EQ
DATE : 12-Oct-22
WIP : 45693

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR FRANCIS GOH MUK HSIUNG
ADDRESS : 17 SELETAR ROAD
#03-31
SINGAPORE 807019
TELEPHONE : HP +65 94772397
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100510066-05
VEHICLE NO : **SLP 8088 T**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 12/6/2017
ENGINE NO : CVK 034006
CHASSIS NO : WAUZZZF54HA032392
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Oct-22
PLACE OF ACCIDENT : CLOSE TO JUNCTION BETWEEN AMK
AVE 3 & CONNECTION PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 8088 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00	?
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	1750 (Without Lock Carrier) 3000 (With Lock Carrier)
TOTAL LABOUR CHARGES		\$ 11,440.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 8088 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	✓ TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, ✓ BONNET, HINGES BOTH FRONT DOORS AND BOTH UPPER A- ✓ PILLARS. ✓ RH ✓	\$ 7,500.00	3300
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 19,132.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,493.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 425.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH <i>?</i>	2	\$ 79.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 144.00	+
7	RADIATOR GRILLE <i>Crushed</i>	1	\$ 2,576.00	✓
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 116.00	+
9	RADIATOR GRILLE COVER - UPPER <i>Smashed</i>	1	\$ 209.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 1,058.00	+
11	FRONT BUMPER REINFORCEMENT BEAM <i>Be</i>	1	\$ 899.00	✓
12	FRONT BUMPER FOAM FILLER PIECE <i>Crushed</i>	1	\$ 139.00	✓
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 82.00	?
14	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 508.00	?
15	FRONT BUMPER TOP COVER <i>delid</i>	1	\$ 143.00	✓
16	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	✓
17	AIR CONDITIONER STICKER	1	\$ 9.00	✓
18	LOCK CARRIER <i>?</i>	1	\$ 154.00	?
19	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 64.00	?
20	HORN HIGH TONE - LH <i>?</i>	1	\$ 134.00	?
SUB TOTAL SPARE PARTS		:	\$ 9,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN LOW TONE - RH ?	1	\$ 139.00	?
22	HORN BRACKET - LH / RH ?	2	\$ 66.00	?
23	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	\$ 531.00	+
24	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	+
25	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 567.00	+
26	FRONT FENDER - LH / RH <i>RH Buckled</i>	2	\$ 2,378.00	1189.
27	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 55.00	+
28	FRONT FENDER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 166.00	+
29	FRONT FENDER BRACKET - LH / RH <i>new</i>	2	\$ 82.00	+
30	FRONT FENDER RIVET <i>new</i>	11	\$ 42.00	✓
31	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH <i>new</i>	2	\$ 110.00	+
32	FRONT FENDER TRIM - LH / RH <i>RH new</i>	2	\$ 342.00	171.
33	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 598.00	+
34	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 164.00	+
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>new</i>	2	\$ 114.00	+
36	FRONT FENDER LEDGE COVER - LH / RH LONG <i>RH ?</i>	2	\$ 80.00	?
37	FRONT FENDER LEDGE COVER - LH / RH SHORT <i>RH ?</i>	2	\$ 36.00	?
38	BONNET <i>Distorted</i>	1	\$ 3,491.00	✓
39	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 128.00	+
40	BONNET HINGE - LH / RH ?	2	\$ 932.00	?
SUB TOTAL SPARE PARTS		:	\$ 10,031.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Me</i>	3	\$ 93.00	✓
42	BONNET ENGINE SOUND ABSORBER ?	1	\$ 382.00	?
43	BONNET STRIKER - LH / RH ?	2	\$ 112.00	?
44	BONNET GAS FILLED STRUT - LH / RH <i>Me</i>	2	\$ 256.00	+
45	BONNET LOCK - LH / RH ?	2	\$ 455.00	?
46	BONNET BOWDEN CABLE - CENTER ?	1	\$ 64.00	?
47	BONNET BOWDEN CABLE COVER ?	1	\$ 11.00	?
48	BONNET RELEASE CABLE - CENTER ?	1	\$ 64.00	?
49	BONNET RELEASE LEVER ?	1	\$ 15.00	?
50	BONNET LOCK CABLE ?	1	\$ 82.00	?
51	WINDSCREEN WIPER SCUTTLE PANEL <i>Me</i>	1	\$ 108.00	+
52	HEADLIGHT - LH / RH <i>RH could, LH?</i>	2	\$ 16,832.00	8416
53	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH ?</i>	2	\$ 89.00	?
54	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH ?</i>	2	\$ 93.00	?
55	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH ?</i>	2	\$ 89.00	?
56	LIFT CYLINDER - LH / RH <i>RH ?</i>	2	\$ 434.00	?
57	LIFT CYLINDER BRACKET - LH / RH <i>RH ?</i>	2	\$ 34.00	?
58	LIFT CYLINDER CORRUGATED PIPE <i>Me</i>	1	\$ 100.00	+
59	LOCK CARRIER ?	1	\$ 1,478.00	?
60	RADIATOR SUPPORT BRACKET - LH / RH <i>could</i>	2	\$ 85.00	✓
SUB TOTAL SPARE PARTS			\$ 20,876.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER <i>new</i>	1	\$ 654.00	<i>x</i>
62	A/C CONDENSER <i>?</i>	1	\$ 683.00	<i>?</i>
63	OUTSIDE TEMPERATURE SENSOR BRACKET <i>?</i>	1	\$ 21.00	<i>?</i>
64	RADIATOR <i>?</i>	1	\$ 1,013.00	<i>?</i>
65	READY-MIX COOLANT <i>?</i>	6	\$ 297.00	<i>?</i>
66	RADIATOR FAN RING <i>?</i>	1	\$ 292.00	<i>?</i>
67	RADIATOR FAN CONTROL UNIT <i>?</i>	1	\$ 2,489.00	<i>?</i>
68	RADIATOR AIR GUIDE - LH / RH INNER <i>?</i>	2	\$ 72.00	<i>?</i>
69	RADIATOR AIR GUIDE - LH / RH OUTER <i>?</i>	2	\$ 38.00	<i>?</i>
70	RADIATOR AIR GUIDE - LOWER <i>?</i>	1	\$ 25.00	<i>?</i>
71	INTAKE AIR DUCT - RH <i>?</i>	1	\$ 25.00	<i>?</i>
72	INTAKE HOSE ENGINE AIR <i>?</i>	1	\$ 61.00	<i>?</i>
73	INTAKE HOSE <i>?</i>	1	\$ 110.00	<i>?</i>
74	AIR FILTER <i>?</i>	1	\$ 418.00	<i>?</i>
75	RADIATOR AIR GUIDE - UPPER <i>?</i>	1	\$ 19.00	<i>?</i>
76	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>new</i>	2	\$ 892.00	<i>x</i>
77	FRONT ROOF CHROME MOLDING - LH / RH <i>Part out</i>	2	\$ 1,412.00	<i>706</i>
78	FRONT WATER DEFLECTOR STRIP - LH / RH <i>new</i>	2	\$ 150.00	<i>x</i>
79	FRONT DOOR CHROME TRIM - LH / RH <i>new</i>	2	\$ 342.00	<i>x</i>
80	FRONT NO PLATE <i>new</i>	S/N	\$ 120.00	<i>x</i>
81	SUNDRIES <i>?</i>		\$ 500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 50,261.00	
TOTAL LABOUR CHARGES		:	\$ 19,132.00	
GRAND TOTAL		:	\$ 69,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian L
13/10/22

we Authorised,

09 Days (Without Lock Carrier)
12 Days (With Lock Carrier)

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: