


PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 8088 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00 ✓	sls.
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	1750 (without Lock Carrier) sls.
TOTAL LABOUR CHARGES		\$ 11,440.00	3000 (with Lock Carrier) sls.

* 3 day additional days.

To add 3 days for the replacement of lock carrier.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Bona



HIA - Adam
- 9 day?

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

1712 SK 1710


DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1 S	2,493.00	✓
2	FRONT BUMPER FIXING PARTS	1 S	425.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH	2 S	79.00	?
4	FRONT BUMPER GRILLE - CENTER	1 S	219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1 S	254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH	2 S	144.00	+
7	RADIATOR GRILLE Cracked	1 S	2,576.00	✓
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2 S	116.00	+
9	RADIATOR GRILLE COVER - UPPER	1 S	209.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 S	1,058.00	+
11	FRONT BUMPER REINFORCEMENT BEAM	1 S	899.00	✓
12	FRONT BUMPER FOAM FILLER PIECE	1 S	139.00	✓
13	FRONT BUMPER GUIDE SECTION - LH / RH	2 S	82.00	?
14	FRONT BUMPER BRACKET - LH / RH	2 S	508.00	254. ✓
15	FRONT BUMPER TOP COVER	1 S	143.00	✓
16	CAUTION SIGN STICKER	1 S	16.00	✓
17	AIR CONDITIONER STICKER	1 S	9.00	✓
18	LOCK CARRIER Bracket cracked	1 S	154.00	✓ H.S.
19	FRONT BUMPER SUPPORT - LH / RH	2 S	64.00	✓ H.S.
20	HORN HIGH TONE - LH	1 S	134.00	?
SUB TOTAL SPARE PARTS			\$ 9,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN LOW TONE - RH ?	1	\$	139.00 ?	
22	HORN BRACKET - LH / RH ?	2	\$	66.00 ?	
23	FRONT PARKING AID SENSOR - INNER <i>Me</i>	2	\$	531.00 +	
24	FRONT PARKING AID SEAL RING <i>Me</i>	4	\$	10.00 +	
25	FRONT BUMPER WIRING SET <i>Me</i>	1	\$	567.00 +	
26	FRONT FENDER - LH (RH) <i>RA Buckled</i>	2	\$	2,378.00 1189.	
27	FRONT FENDER ATTACHMENT PARTS <i>Me</i>	1	\$	55.00 +	
28	FRONT FENDER CLOSING ELEMENT - LH / RH <i>Me</i>	2	\$	166.00 +	
29	FRONT FENDER BRACKET - LH / RH <i>Me</i>	2	\$	82.00 +	
30	FRONT FENDER RIVET <i>Me</i>	11	\$	42.00 -	
31	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH <i>Me</i>	2	\$	110.00 +	
32	FRONT FENDER TRIM - LH (RH) <i>RA</i>	2	\$	342.00 171.	
33	FRONT WHEEL HOUSING LINER - LH / RH <i>Me</i>	2	\$	598.00 +	
34	FRONT WHEEL SPOILER - LH / RH <i>Me</i>	2	\$	164.00 +	
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>Me</i>	2	\$	114.00 +	
36	FRONT FENDER LEDGE COVER - LH / RH LONG RH <i>del</i>	2	\$	80.00 → 40 ?	
37	FRONT FENDER LEDGE COVER - LH / RH SHORT RH <i>del</i>	2	\$	36.00 → 18 ?	
38	BONNET <i>Distorted</i>	1	\$	3,491.00 ✓	
39	BONNET ATTACHMENT PARTS <i>Me</i>	1	\$	128.00 +	
40	BONNET HINGE - LH / RH ?	2	\$	932.00 ?	
SUB TOTAL SPARE PARTS			\$	10,031.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST


LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Mr</i>	3	\$ 93.00	✓
42	BONNET ENGINE SOUND ABSORBER ?	1	\$ 382.00	?
43	BONNET STRIKER - LH / RH <i>RH Best</i>	2	\$ 112.00	✓ 56. <i>18/5</i>
44	BONNET GAS FILLED STRUT - LH / RH <i>Mr</i>	2	\$ 256.00	✓
45	BONNET LOCK - LH / RH <i>RH Dmgd</i>	2	\$ 455.00	✓ 227.50 <i>18/5</i>
46	BONNET BOWDEN CABLE - CENTER <i>Damaged</i>	1	\$ 64.00	✓
47	BONNET BOWDEN CABLE COVER ?	1	\$ 11.00	?
48	BONNET RELEASE CABLE - CENTER ?	1	\$ 64.00	?
49	BONNET RELEASE LEVER ?	1	\$ 15.00	?
50	BONNET LOCK CABLE ?	1	\$ 82.00	?
51	WINDSCREEN WIPER SCUTTLE PANEL <i>Mr</i>	1	\$ 108.00	✓
52	HEADLIGHT - LH / RH <i>RH could, LH ?</i>	2	\$ 16,832.00	8416.
53	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH</i>	2	\$ 89.00	?
54	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH</i>	2	\$ 93.00	?
55	HEADLIGHT COMPENSATING PIECE - LH / RH <i>RH</i>	2	\$ 89.00	?
56	LIFT CYLINDER - LH / RH <i>RH</i>	2	\$ 434.00	?
57	LIFT CYLINDER BRACKET - LH / RH <i>RH Dmgd</i>	2	\$ 34.00	✓ 17 <i>18/5</i>
58	LIFT CYLINDER CORRUGATED PIPE <i>Mr</i>	1	\$ 100.00	✓
59	LOCK CARRIER <i>cracked</i>	1	\$ 1,478.00	✓ <i>18/5</i>
60	RADIATOR SUPPORT BRACKET - LH / RH <i>could</i>	2	\$ 85.00	✓
SUB TOTAL SPARE PARTS			\$ 20,876.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 8088 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER <i>Me a</i>	1	\$ 654.00	✓
62	A/C CONDENSER <i>Dented</i>	1	\$ 683.00	✓
63	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Me a</i>	1	\$ 21.00	✓
64	RADIATOR <i>Dented</i>	1	\$ 1,013.00	✓
65	READY-MIX COOLANT <i>Me a</i>	6	\$ 297.00	✓
66	RADIATOR FAN RING ?	1	\$ 292.00	?
67	RADIATOR FAN CONTROL UNIT ?	1	\$ 2,489.00	?
68	RADIATOR AIR GUIDE - LH / RH INNER <i>RH could</i>	2	\$ 72.00	✓
69	RADIATOR AIR GUIDE - LH / RH OUTER <i>De Ld</i>	2	\$ 38.00	✓
70	RADIATOR AIR GUIDE - LOWER ?	1	\$ 25.00	?
71	INTAKE AIR DUCT - RH ?	1	\$ 25.00	?
72	INTAKE HOSE ENGINE AIR <i>Int</i>	1	\$ 61.00	✓
73	INTAKE HOSE ?	1	\$ 110.00	?
74	AIR FILTER ?	1	\$ 418.00	?
75	RADIATOR AIR GUIDE - UPPER ?	1	\$ 19.00	?
SK - 76	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>Me a</i>	2	\$ 892.00	✓
SK - 77	FRONT ROOF CHROME MOLDING - LH / RH <i>RH cut</i>	2	\$ 1,412.00	706
78	FRONT WATER DEFLECTOR STRIP - LH / RH <i>Me a</i>	2	\$ 150.00	✓
79	FRONT DOOR CHROME TRIM - LH / RH <i>Me a</i>	2	\$ 342.00	✓
80	FRONT NO PLATE <i>Me a</i>	S/N	\$ 120.00	✓
81	SUNDRIES ?	\$	\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 50,261.00	
TOTAL LABOUR CHARGES		:	\$ 19,132.00	
GRAND TOTAL		:	\$ 69,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.