

SMH3134G

Mazda 6

JM6GL1072K0311705

Rear Bumper	Debond	1009	✓
Rear Bumper Clips	new	50(SN)	✓
Rear Bumper Side Holder	x02 ^{HP} new	41 x 2 = 82	X
Rear Bumper Reinforcement	Dented	539	✓
Rear Bumper Tow Covers	x02 ^{RT} Debond	47 x 2 = 94	47
Rear Bumper Reflector	x02 ^{HP} new	42 x 2 = 84	+
Rear Bumper Centre Guide	Debond	125	✓
Rear End Panel	Repair	698	+
Rear End Panel Top Garnish	} ^{HP} new	189	+
Rear End Panel Top Garnish Clips		50(SN)	+
Rear End Panel Sealant		60(SN)	+
Taillamp	x02 Cut	1592 x 2 = 3184	✓
Bootlid	Repair	1135	+
Bootlid Lock	Buy	184	✓

SMH3134G.

Bootlid Weatherstripe . New 195 +

Bootlid Reflector x 02 ut

974 x 2 = 1948 ✓

Mazda 6 Wording } ✓

58 ✓

SkyActiv Emblem . New ✓

74 ✓

Mazda Logo ✓

55 ✓


Reverse Sensor x 04. 2 pieces changed

203 x 4 = ~~812~~ 406

7629.

S.N. 50

less 20%: 6103:20



SMH31346.

Panel Beating

~~1200~~ 600

Spray Painting.

~~1200~~ 600

Wiring

~~100~~ 30

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~150~~ 50

To transfer bootlid fittings

150 +

To apply tuff coat.

~~150~~ 50

1380

total: 7533.20.

L/s: 6k.

OH Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: