## **COMFORTDELGRO ENGINEERING PTE LTD**

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SH7921D

MAKE

REG.28.01.2021

12.10.2022

CHIANG/INCOME

MODEL

IONIQ G3

Qty	Parts Description/ Labour	Type		Amount
	1 REAR BUMPER / (M)	.,,,,		\$459.40
	1 REAR BUMPER SIDE BRACKET LH/RH X		\$55.80	\$111.60
	1 REAR BUMPER CENTRE MOULDING / RE		,	\$451.25
	REAR BUMPER REINFORCEMENT STAY LH/RH	N	\$138.10	\$276.20
	1 REAR BUMPER REINFORCEMENT X NN		,	\$394.80
	1 REAR BUMPER LOWER CENTRE MOULDING	wt		\$155.00
	1 REAR BUMPER FOG LAMP X NN			\$201.50
	1 SMART KEY SENSOR X NN			\$40.50
:	1 REAR BUMPER NUMBER LAMP LH/RH			\$85.30
	1 TOWING COVER X NN			\$98.80
	REAR BUMPER CLIPS / MC		\$2.20	\$22.00
	SUB TOTAL			\$2,296.35
	20.00%			\$459.27
	DISCOUNTED TOTAL			\$1,837.09
:	REAR NUMBER PLATE W/HOLDER / M'S			\$55.00
	REAR REVERSE SENSOR 🙎 NN			\$180.00
	,,,,,,			\$211.50
				-10%: 49.5
	Labour Charge			10701 1010
	Panel Beating			\$550.00
	Spray Painting Charge			\$300.00
	Tuff Kote			\$60.00
	Remove/refix Reverse sensor			\$60.00
	TOTAL LABOUR			\$970.00
	FCTIMANT TOTAL			
	ESTIMATE TOTAL			\$3,018.59
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Mays. L/S Gn. as 13/10 4pm

Living to a nouny

the Rupanier into a said

Coresurvey Letin and a structing

I capital damage and requirement on

I provide and and

I contact a tweyed and

I capital provide a said and

I capital provide a said and

I capital provide and

I capital provide and

1559.62