

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22010184/KCY3E2
Date: 30/11/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1001981941	
Claimant Vehicle No : SMY6064R	Insured Vehicle No : SNB93E	
Date of Loss: 01/10/2022	Nature of Claim: TP	Claim No: 286684

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMY6064R		
Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No: 2ZR0F41904	
Reg. Date: 17/03/2021 (Man. Year: 2020)	Chassis No: ZWR800439098	
Colour: Metallic Black	Odometer: 131048 km	
Engine Capacity: 1797 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15	
Front Left Side: Davanti 8 mm	Rear Left Side: Davanti 8 mm	
Front Right Side: Davanti 8 mm	Rear Right Side: Davanti 8 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,327.65	1,022.61	1,305.04	56.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	910.00	1,120.00	55.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,357.65	1,932.61	2,425.04	55.65
Approved Total (Overridden) (\$\$)		1,550.00		
(\$\$)	4,357.65	1,550.00	2,807.65	64.43
+ GST 7.00/7.00% (\$\$)	305.04	108.50	196.54	64.43
Nett Amount (\$\$)	4,662.69	1,658.50	3,004.19	64.43

INSPECTION

Date of Assignment: 14/10/2022	
Date Inspected: 14/10/2022	Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair: 4.0 days	

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2022)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY6064R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Bent	1,363.48 FL	*1,363.48 FL
2	1		*REAR FENDER - LH	Repair	1,740.05 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					3,103.53	1,363.48
- List Item Discount on L Items 25.00/25.00% (S\$)					775.88	340.87
Total Parts (S\$)					2,327.65	1,022.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER DOOR MOTOR, GEAR & MECHANISMS TO NEW DOOR	New	180.00	60.00
2	TO PULL, KNOCK & ADJUST AFFECTED AREAS	New	850.00	450.00
3	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,030.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >