

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURA	NCE BHD	Ref:	CS/LPC22010185/Rwy3	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date	e: 14/10/2022	
			Cod	e: LPC2	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 131L	Veh. Inspected	SBS 5023C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/22/VP05/026409	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	14/10/2022	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.					
	Accident Date	11/10/2022	Inspection Date	14/10/2022	
	Survey held at	15 ANG MO KIO ST 63 SINGAPORE 569117			
	Repairer	SBS TRANSIT LTD (HQ)			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				