



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22007530/Kcy3e2-1 Date: 08/12/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 9058U	Veh. Inspected	SGJ 132S
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/026119	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	13/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI RS7 (A)	c.c	3996
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	WUAZZZF27MN902831	Colour	METALLIC GREY
	Odometer	10948 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	285/30Z R22	PIRELLI	7 mm
	L/H Front Tyre	285/30Z R22	PIRELLI	7 mm
	R/H Rear Tyre	285/30Z R22	PIRELLI	7 mm
	L/H Rear Tyre	285/30Z R22	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S DOOR. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/08/2022	Inspection Date	12/08/2022
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	