



KTO Automobile Assessors

470 Segar Road #09-232 Singapore 670470 Email: ktoa@singnet.com.sg HP: 98505311

Reg. No: 52941122M

Paper Survey
PRS done by you.
Thank you.

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : Ow Wai Leong Jason (Ou WeiLiang)
C/O Thiam Heng Huat Pte Ltd
Blk 176 Sin Ming Drive #05-14
Sin Ming Autocare Singapore 575721

Date : 31 August 2022
Our Ref : TP/THH/SGJ132S/8703

REFERENCE PARTICULARS

Date of Accident : 04 August 2022
Date of Inspection : 05 August 2022

Type of Inspection : Third Party Claim
Date of Re-Inspn : 16 August 2022

VEHICLE PARTICULARS

Registration No : SGJ 132 S
Make : Audi
Model : RS7 Sportback 4.0 TFSI QU
Year : 2021 (COE Expiry 07 Feb 2031)

Engine No : DJP007506
Chassis No : WUAZZZF27MN902831
Odometer : 10948 km
Colour : Grey

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)


Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near side	Pirelli	285/30R22	8 mm
Front Off Side	Pirelli	285/30R22	8 mm
Rear Near Side	Pirelli	285/30R22	8 mm
Rear off Side	Pirelli	285/30R22	8 mm

GENERAL DESCRIPTION OF DAMAGES



The vehicle sustained damage at the off side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$12,500.00 nett** at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Six (6) working days.

3 days

Enclosed Thirty-Two (32) photographs depicting damage to the vehicle and after repair.

Inspection conducted at : Blk 176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Name of Workshop : Thiam Heng Huat Pte Ltd

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

Automobile Consultants, Insurance Loss Assessors / Adjusters, Inspection and Evaluation

VEHICLE NO : SGJ 132 S
MAKE/MODEL : AUDI RS7 SPORTBACK 4.0 TFSI QU

Our Ref : TP/THH/SGJ132S/8703

WUA 787F 27 JAN 90 2831

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS					
A) SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED	
	PC/SET	CONDITION	QUOTATION	QUOTATION	
1 Rear door RH → 521F	1	Dented/Grazed	\$ 12,700.00	\$ 12,700.00	
2 Rear door outside handle RH	1	Serviceable	\$ 286.50	~	
3 Rear door window aperture seal RH	1	Necessary	\$ 257.00	\$ 257.00	
4 Rear door inner seal RH	1	Necessary	\$ 220.00	\$ 220.00	
5 Rear door outer seal RH	1	Necessary	\$ 170.00	\$ 170.00	
6 Rear door trim panel clips RH	1 set	Necessary	\$ 34.00	\$ 34.00	
Parts Total :			\$ 13,667.50	\$ 13,381.00	
B) <u>LABOUR CHARGES & MISC</u>					
7 Spray painting on rear door/outside handle & repaired parts including supply of paint materials.			\$ 900.00	\$ 600.00	30d
8 Remove damaged parts, knock out dents, remove & reinstall necessary fittings to facilitate, repairs, reshape, refit, adjust, replace and realign all relevant parts.			\$ 950.00	\$ 650.00	25d
9 To carry out diagnostic checks & reset.			\$ 580.00	\$ 380.00	18d
10 Check wiring, re-connection socket, lighting system, power window & central locking system for proper function.			\$ 120.00	\$ 50.00	2d
11 To transfer rear door mechanism & components.			\$ 120.00	\$ 60.00	
12 To re-wrap rear door paint protection film.			\$ 480.00	\$ 480.00	25d
13 To cavity preservation on all affected areas.			\$ 100.00	\$ 60.00	3d
Labour Total :			\$ 3,250.00	\$ 2,280.00	
Total Parts and Labour			\$ 16,917.50	\$ 15,661.00	
<u>FINAL LUMP SUM ADJUSTMENT</u>				<u>\$ 12,500.00</u>	

POINT OF IMPACT

The impact was confined to the off side portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

VEHICLE NO : 10071223
MAKE/MODEL : AUDI RS7 SPORTBACK 4.0 TFSI QU

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$12,500.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser