

ASS. REC. BY:

REF:

AI6/ 22010193/kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s CPTIMS

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

100m

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PNG 88946 Yr Regn: 09, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1797

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 7216 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD7S3E400J068324

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/10/22

D.O.I. 14/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/10 @ 3983-30 Center

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Date: 13/10/2022

Vehicle No: SNG8894G

Model: TOYOTA PRIUS PLUS

Chassis: JTDZSEU00J068324-2021

Reg.Year: 2022

NOT Authorised
Accounting B & paint
4 days
83983.30

Third Party Insurer: AIG

Third Party Veh No: SFY6999B

Date of Accident: 11/10/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>929</i>	1		<i>RM</i> \$1,096.00
2	REAR TAILGATE "PRIUS PLUS " EMBLEM	1		<i>RM</i> \$77.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>RM</i> \$68.00
4	REAR TAILGATE INNER TRIM BOARD	1		<i>RM</i> \$355.00
5	REAR TAILGATE INNER LOCK	1		<i>R</i> \$425.00
6	REAR TAILGATE WEATHERSTRIP	1		<i>RM</i> \$362.00
7	REAR WINDSCREEN MOULDING	1		<i>RM</i> \$75.00
8	REAR BUMPER <i>549.40</i>	1		<i>Bu</i> \$589.00
9	REAR BUMPER SIDE BRACKET LH	1		<i>CM</i> \$144.00
10	REAR BUMPER SIDE BRACKET RH	1		<i>CM</i> \$144.00
11	REAR BUMPER LOWER LIP <i>698</i>	1		<i>RM</i> \$726.00
12	REAR BUMPER REINFORCEMENT	1		<i>RM</i> \$225.00
13	REAR END PANEL	1		<i>R</i> \$696.00
14	REAR END PANEL UPPER COVER	1		<i>my cm</i> \$175.00
15	REAR FLOOR PANEL TOOLBOX TRAY	1		<i>RM</i> \$427.00
16	REAR FLOOR PANEL TOOLBOX UPPER BOARD	1		<i>RM</i> \$542.00
SUB TOTAL				\$6,126.00
LESS 25%				-\$1,531.50
PARTS TOTAL				\$4,594.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>RM</i> \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>RM</i> \$50.00
3	REAR BUMPER CLIPS	1		<i>RM</i> \$50.00
4	REAR BUMPER REVERSE SENSOR	1		<i>RM</i> \$300.00
5	REAR END PANEL JOINT SEALANT	1		<i>RM</i> \$80.00
6	REAR END PANEL UPPER COVER CLIPS	1		<i>RM</i> \$40.00
S/N TOTAL				\$600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500 | Bk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Signature:

Date:



Date: 13/10/2022
 Vehicle No: SNG8894G
 Model: TOYOTA PRIUS PLUS
 Chassis: JTDZSEU00J068324-2021
 Reg.Year: 2022

Third Party Insurer: AIG
 Third Party Veh No: SFY6999B
 Date of Accident: 11/10/2022
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	500 \$700.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	600 \$700.00
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	120 \$150.00
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00 60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00 50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00 30
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	nn \$100.00 X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00 20
LABOUR TOTAL	\$2,090.00

TING AN	TOTAL	\$7,284.50
----------------	--------------	-------------------