

Date: 13/10/2022

Vehicle No: SNG8894G

Model: TOYOTA PRIUS PLUS

Chassis: JTDZSEU00J068324-2021

Reg.Year: 2022

*NOT Authorised
Returning B & paint
4 days*

Third Party Insurer: AIG

Third Party Veh No: SFY6999B

Date of Accident: 11/10/2022

Estimator:

TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bu</i> \$1,096.00 ✓
2	REAR TAILGATE "PRIUS PLUS " EMBLEM	1		<i>na</i> \$77.00 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$68.00 ✓
4	REAR TAILGATE INNER TRIM BOARD	1		<i>in</i> \$355.00 X
5	REAR TAILGATE INNER LOCK	1		<i>R</i> \$425.00 X
6	REAR TAILGATE WEATHERSTRIP	1		<i>in</i> \$362.00 X
7	REAR WINDSCREEN MOULDING	1		<i>na</i> \$75.00 ✓
8	REAR BUMPER	1		<i>Bu</i> \$589.00 ✓
9	REAR BUMPER SIDE BRACKET LH	1		\$144.00 ?
10	REAR BUMPER SIDE BRACKET RH	1		\$144.00 ?
11	REAR BUMPER LOWER LIP	1		<i>pu</i> \$726.00 ✓
12	REAR BUMPER REINFORCEMENT	1		\$225.00 ?
13	REAR END PANEL	1		<i>R</i> \$696.00 X
14	REAR END PANEL UPPER COVER	1		\$175.00 ?
15	REAR FLOOR PANEL TOOLBOX TRAY	1		<i>in</i> \$427.00 X
16	REAR FLOOR PANEL TOOLBOX UPPER BOARD	1		<i>in</i> \$542.00 X
SUB TOTAL				\$6,126.00
LESS 25%				-\$1,531.50
PARTS TOTAL				\$4,594.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$80.00 <i>405a</i>
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>na</i> \$50.00 X
3	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
4	REAR BUMPER REVERSE SENSOR	1		<i>pu</i> \$300.00 <i>200a</i>
5	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$80.00 X
6	REAR END PANEL UPPER COVER CLIPS	1		<i>na</i> \$40.00 X
S/N TOTAL				\$600.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/10/2022
 Vehicle No: SNG8894G
 Model: TOYOTA PRIUS PLUS
 Chassis: JTDZSEU00J068324-2021
 Reg.Year: 2022

Third Party Insurer: AIG
 Third Party Veh No: SFY6999B
 Date of Accident: 11/10/2022
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	500 \$700.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	600 \$700.00
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	120 \$150.00
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00 60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00 50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00 30
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$100.00 7
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00 20
LABOUR TOTAL	\$2,090.00

TING AN	TOTAL	\$7,284.50
---------	--------------	-------------------

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

