

ASS. REC. BY:

REF:

A61 22 010196/Kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Lum Sum:

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Veh No:

SMN 4687P

Yr Regn:

08, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1896

Colour

M.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

100797

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU3

1319310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

P-1000

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Report Format :

Lump Sum / I.B.I. (\$

Date: 13/10/2022
Vehicle No: SMN4687P
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31319310 - 2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: GBF6097B
Date of Accident: 13/10/2022
Estimator: KIT
Surveyor:

Not Authorised
11/10/22
Per survey After Paint
4-5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		\$1,068.10
2	REAR TAILGATE WINDSCREEN MOULDING	1		\$138.60
3	REAR TAILGATE "LOGO" EMBLEM	1		\$52.50
4	REAR TAILGATE "VEZEL" EMBLEM	1		\$58.80
5	REAR TAILGATE "HYBRID" EMBLEM	1		\$57.90
6	REAR TAILGATE LAMP LH	1		\$480.80
7	REAR TAILGATE OUTER CHROME MOULDING	1		\$112.50
8	REAR TAILGATE MECHANISM LOCK	1		\$96.40
9	REAR TAILGATE INNER TRIM BOARD	1		\$155.20
10	REAR TAILGATE WEATHERSTRIP	1		\$105.20
11	REAR TAILLAMP LH	1		\$520.70
12	REAR BUMPER	1		\$858.60
13	REAR BUMPER SIDE RETAINER LH	1		\$26.50
14	REAR BUMPER REFLECTOR LH	1		\$178.50
15	REAR BUMPER INNER BUZZER	1		\$110.10
16	REAR END PANEL	1		\$484.10
17	REAR END PANEL TOP GARNISH	1		\$103.60
SUB TOTAL				\$4,608.10
LESS 20%				\$921.62
PARTS TOTAL				\$3,686.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		\$80.00
2	REAR NUMBER PLATE WITH HOLDER	1		\$50.00
3	REAR TAILGATE INNER TRIM BOARD CLIPS	1		\$30.00
4	REAR BUMPER CLIPS	1		\$50.00
5	REAR BUMPER REVERSE SENSOR	1		\$300.00
6	REAR END PANEL TOP GARNISH CLIPS	1		\$30.00
7	REAR END PANEL JOINT SEALANT	1		\$60.00
SUB TOTAL				\$600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554909
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Acknowledged by Repairer

Signature: _____

Date: _____



Date: 13/10/2022
Vehicle No: SMN4687P
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31319310 - 2018
Reg. Year: 2019

Third Party Insurer: AIG
Third Party Veh No: GBF6097B
Date of Accident: 13/10/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.	\$700.00	?
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.	\$700.00	600/
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$120.00	✓
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & BACK TO ORIGINAL OPERATIONS.	\$100.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.	\$100.00	50/
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$80.00	7
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$80.00	7
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	20/
LABOUR TOTAL		\$1,960.00
KIT	TOTAL	\$6,246.48

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 227K

Vehicle Details

Vehicle No.: SMN4687P

Vehicle to be Exported: No

Intended Deregistration Date: 14 Oct 2022

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: White

Manufacturing Year: 2018

Engine No.: LEB6739325

Chassis No.: RU31319310

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$27,731.00

Original Registration Date: 13 Aug 2019

First Registration Date: 13 Aug 2019

Transfer Count: 0

Actual ARF Paid: \$20,824.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Aug 2029

PARF Rebate Amount: \$15,618.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2029

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$40,001.00

COE Rebate Amount: \$27,312.00

Total Rebate Amount: \$42,930.00

The information contained herein is correct as at 13 Oct 2022

OK