

ASS. REC. BY:

REF:

A/G/ 22 01 01 96 /kp

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 4687P

Yr Regn:

08, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Venz

c.c

1496

Colour

M.P. white

A/C:

Insured / Std / Nil / NA

Sp. Reading

100797

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

RU3

1319310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F. Farroad

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

mm

L/Bal.

mm

D.O.A.

13/10/22

L/Bal.

mm

D.O.I.

14/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

11/12 11 PM 8 2700h Car

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fines

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Date: 13/10/2022

Vehicle No: SMN4687P

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31319310 - 2018

Reg.Year: 2019

Third Party Insurer: AIG

Third Party Veh No: GBF6097B

Date of Accident: 13/10/2022

Estimator: KIT

Surveyor:

Not Authored
11 Sep @ 2700h
Resurvey After Paint
4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>953</i>	1		<i>By</i> \$1,068.10
2	REAR TAILGATE WINDSCREEN MOULDING	1		<i>na</i> \$138.60
3	REAR TAILGATE "LOGO" EMBLEM	1		<i>na</i> \$52.50
4	REAR TAILGATE "VEZEL" EMBLEM	1		<i>na</i> \$58.80
5	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$57.90
6	REAR TAILGATE LAMP LH	1		<i>na</i> \$480.80
7	REAR TAILGATE OUTER CHROME MOULDING	1		<i>na</i> \$112.50
8	REAR TAILGATE MECHANISM LOCK	1		<i>na</i> \$96.40
9	REAR TAILGATE INNER TRIM BOARD	1		<i>na</i> \$155.20
10	REAR TAILGATE WEATHERSTRIP	1		<i>na</i> \$105.20
11	REAR TAILLAMP LH	1		<i>na</i> \$520.70
12	REAR BUMPER <i>762.00</i>	1		<i>na</i> \$858.60
13	REAR BUMPER SIDE RETAINER LH	1		<i>na</i> \$26.50
14	REAR BUMPER REFLECTOR LH	1		<i>na</i> \$178.50
15	REAR BUMPER INNER BUZZER	1		<i>na</i> \$110.10
16	REAR END PANEL	1		<i>na</i> \$484.10
17	REAR END PANEL TOP GARNISH	1		<i>na</i> \$103.60
SUB TOTAL				\$4,608.10
LESS 20%				\$921.62
PARTS TOTAL				\$3,686.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		<i>na</i> \$80.00
2	REAR NUMBER PLATE WITH HOLDER	1		<i>na</i> \$50.00
3	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>na</i> \$30.00
4	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
5	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00
6	REAR END PANEL TOP GARNISH CLIPS	1		<i>na</i> \$30.00
7	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$60.00
SUB TOTAL				\$600.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554609
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Acknowledged by Repairer

Branch (Motor Insurance Claims)
Signature: _____ Date: _____
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/10/2022
Vehicle No: SMN4687P
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31319310 - 2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: GBF6097B
Date of Accident: 13/10/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.	\$700.00	500
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.	\$700.00	600
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$120.00	✓
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & BACK TO ORIGINAL OPERATIONS.	\$100.00	600
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.	\$100.00	500
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$80.00	300
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$80.00	✓
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	200
LABOUR TOTAL		\$1,960.00
KIT	TOTAL	\$6,246.48

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

