

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR 286/G Yr Regn: 8/8/17Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merch 3 c.c. 1496Colour: White A/C: Insured / Std / Nil / NASp. Reading: 210178 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 3M63N 922811015733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 11/10/22 D.O.I. 11/10/22Survey held at Lion City

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MIV 66K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B. (\$ _____)



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Allianz Insurance Singapore Pte. Ltd

Date : 13 Oct 2022

Attn : MOTOR CLAIMS DEPT

Star (LKK)

14/10/22, 11:30pm

W R

L/S

by AL

ESTIMATE

3 45

VEHICLE NO. : SLR2861G
CHASSIS NO : JM6BN22A8H0157313
MAKE / MODEL : Mazda 3
DATE OF ACCIDENT: 11 Oct 2022
YOUR INSURED VEHICLE NUMBER : SMJ3991M

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front RH door mirror / GR	1PC	\$320.00	\$320.00
2	Front RH door mirror cover / M/S	1PC	\$130.00	\$130.00
3	Front RH mirror glass / M/S	1PC	\$70.00	\$70.00
LIST TOTAL S\$:				\$520.00
20.00% DISCOUNT S\$:				\$104.00
				\$416.00

LABOUR CHARGES

- 1 To labour charge FRONT RH S MIRROR out to facilitate repairs and replacement of damage parts \$300.00 1.00
- 2 To respray front RH wing mirror cover \$300.00 2.00
- 3 To apply rustproofing on all damaged parts \$200.00 X
- 4 Transfer and test front RH side wingmirror mechanism \$180.00 X
- 5 To check wiring system \$200.00 3.00

LABOUR TOTAL S\$:	\$1,180.00
TOTAL S\$:	\$1,596.00
7% GST	\$111.72
GRAND TOTAL S\$:	\$1,707.72