

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 08.10.2022

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SGG4115G**
MODEL : **HONDA CIVIC**
DATE OF ACCIDENT : 07.10.2022
TIME OF ACCIDENT : 18:10HRS

FK71001204
Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR SIDE MIRROR LH <i>new</i>	1	\$ 979.20	\$ 979.20
2	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,294.30	\$ 1,294.30
3	FRONT DOOR OUTER HANDLE LH <i>new</i>	1	\$ 277.60	\$ 277.60
4	FRONT DOOR KEY LOCK LH <i>new</i>	1	\$ 169.40	\$ 169.40
5	FRONT DOOR STOPPER LH <i>new</i>	2	\$ 16.20	\$ 32.40
6	FRONT DOOR TOP MOULDING LH <i>new</i>	1	\$ 134.60	\$ 134.60
7	FRONT DOOR HINGE LH <i>new</i>	2	\$ 59.80	\$ 119.60
8	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 196.30	\$ 196.30
9	FRONT DOOR INNER TRIM LH <i>new</i>	1	\$ 678.90	\$ 678.90
10	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 329.80	\$ 329.80
11	FRONT DOOR LOCK CATCHER LH <i>new</i>	1	\$ 54.30	\$ 54.30
12	FRONT DOOR WEATHER STRIP LH <i>new</i>	1	\$ 137.20	\$ 137.20
13	FRONT DOOR OUTER STRIP LH <i>new</i>	1	\$ 120.10	\$ 120.10
14	FRONT DOOR LOWER INNER RUBBER LH <i>new</i>	1	\$ 59.60	\$ 59.60
15	FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR LH <i>new</i>	1	\$ 399.40	\$ 399.40
16	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 79.40	\$ 79.40
17	CENTER PILLAR (OUTER) LH <i>Distorted</i>	1	\$ 1,249.30	\$ 1,249.30
18	CENTER PILLAR (INNER) LH <i>new</i>	1	\$ 1,089.70	\$ 1,089.70
19	CENTER PILLAR INNER TRIM LH <i>new</i>	1	\$ 289.60	\$ 289.60
20	ROCKER PANEL LH (OUTER) <i>Distorted</i>	1	\$ 429.80	\$ 429.80
21	SIDE SKIRT LH <i>new</i>	1	\$ 510.00	\$ 510.00
22	SIDE SKIRT SPOILER LH <i>new</i>	1	\$ 486.20	\$ 486.20

+
✓
✓
+
+
+
+
✓
545
+
+
+
+
+
+
798
+
+
+
✓
✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGG4115G**
 MODEL : **HONDA CIVIC**
 DATE OF ACCIDENT : 07.10.2022
 TIME OF ACCIDENT : 18:10HRS

23	REAR DOOR LH <i>Distorted</i>	1	\$ 1,291.70	\$ 1,291.70	✓
24	REAR DOOR WIRE HARNESS LH <i>new</i>	1	\$ 421.60	\$ 421.60	+
25	REAR DOOR FRAME STEP GARNISH LH <i>new</i>	1	\$ 89.40	\$ 89.40	+
26	REAR DOOR OUTER HANDLE LH <i>new</i>	1	\$ 269.50	\$ 269.50	✓
27	REAR DOOR LOWER RUBBER LH <i>new</i>	1	\$ 55.70	\$ 55.70	+
28	REAR DOOR HINGE LH <i>Best</i>	2	\$ 52.70	\$ 105.40	✓
29	REAR DOOR CHECKER LH <i>new</i>	1	\$ 98.40	\$ 98.40	+
30	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 234.60	\$ 234.60	✓
31	REAR DOOR LOCK CATCHER LH <i>new</i>	1	\$ 25.40	\$ 25.40	+
32	REAR DOOR INNER TRIM LH <i>new</i>	1	\$ 654.20	\$ 654.20	✓ 577
33	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 118.60	\$ 118.60	✓
34	REAR DOOR POWER WINDOW MOTOR C/W REGULATOR LH <i>new</i>	1	\$ 341.70	\$ 341.70	✓
35	REAR DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 65.80	\$ 65.80	+
36	REAR DOOR OUTER STRIP LH <i>new</i>	1	\$ 108.70	\$ 108.70	+
37	REAR DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 155.80	\$ 155.80	+
38	REAR FENDER LH <i>Best</i>	1	\$ 989.70	\$ 989.70	+
39	REAR FENDER COWLING LH <i>new</i>	1	\$ 172.20	\$ 172.20	✓
40	REAR LOWER ARM LH <i>Best</i>	1	\$ 198.30	\$ 198.30	✓
41	REAR UPPER ARM LH <i>Best</i>	1	\$ 208.40	\$ 208.40	+
42	REAR SWING ARM LH <i>Best</i>	1	\$ 289.40	\$ 289.40	✓
43	REAR SHOCK ABSORBER LH <i>new</i> nec	1	\$ 321.50	\$ 321.50	✓
44	REAR LINKAGE LH <i>new</i>	1	\$ 98.70	\$ 98.70	✓
45	REAR WHEEL HUP C/W BEARING LH <i>new</i>	1	\$ 389.60	\$ 389.60	✓
46	REAR KNUCKLE ARM LH <i>new</i>	1	\$ 347.80	\$ 347.80	✓
47	REAR ABS SENSOR LH <i>new</i>	1	\$ 298.80	\$ 298.80	+
48	REAR BUMPER <i>Best</i>	1	\$ 1,294.30	\$ 1,294.30	855
49	REAR BUMPER SIDE DIFFUSER <i>new</i>	1	\$ 894.30	\$ 894.30	+
50	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 156.20	\$ 156.20	+

10195.40
 8156.32

TOTAL PRICE \$ 18,812.40
 LESS 20% \$ 3,762.48
SUB TOTAL PRICE \$ 15,049.92

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	CENTER PILLAR (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00

60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGG4115G**
 MODEL : **HONDA CIVIC**
 DATE OF ACCIDENT : 07.10.2022
 TIME OF ACCIDENT : 18:10HRS

2	SIDE SKIRT CLIP (SET) <i>Mr</i>	1	\$ 80.00	\$ 80.00	30
3	REAR FENDER SEALANT LH <i>Mr</i>	1	\$ 150.00	\$ 150.00	60
4	REAR FENDER COWLING CLIP LH <i>Mr</i>	1	\$ 60.00	\$ 60.00	30
5	CENTER PILLAR STICKER <i>Mr</i>	1	\$ 30.00	\$ 30.00	✓
6	REAR FENDER SIDE GARNISH SEALANT LH <i>Mr</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER GARNISH INNER SEAL LH <i>Mr</i>	1	\$ 60.00	\$ 60.00	+
8	REAR WHEEL TYRE LH <i>Mr</i>	1	\$ 800.00	\$ 800.00	+
9	REAR WHEEL RIM LH <i>Mr</i>	1	\$ 850.00	\$ 850.00	550
10	WHEEL CAP (SET) <i>Mr</i>	1	\$ 120.00	\$ 120.00	+
11	REAR BUMPER CLIP (SET) <i>Mr</i>	1	\$ 80.00	\$ 80.00	30
12	BRAKE OIL <i>Mr</i>	1	\$ 30.00	\$ 30.00	+

TOTAL \$ 2,490.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,800.00	1300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1300
3	WIRING CHECK	\$ 250.00	30
4	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	120
5	REMOVE AND REFIX SAFETY BELT	\$ 250.00	100
6	REMOVE AND REFIX FRONT DOOR WINDOW GLASS	\$ 120.00	40
7	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	40
8	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	220
9	FOUR WHEEL ALIGNMENT	\$ 120.00	80
10	REMOVE AND REFIX REAR DOOR WINDOW GLASS	\$ 120.00	40
11	TRANSFER REAR DOOR MECHANISM	\$ 80.00	40

790

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGG4115G**
 MODEL : **HONDA CIVIC**
 DATE OF ACCIDENT : 07.10.2022
 TIME OF ACCIDENT : 18:10HRS

12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50
13	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
14	REMOVE AND REFIX REAR FENDER GARNISH LH	\$ 80.00	X
15	RESET ABS LIGHT	\$ 350.00	X
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

3360

TOTAL \$ 7,430.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,539.92
 TOTAL LABOUR COST : \$ 7,430.00
 TOTAL REPAIR COST : \$ 24,969.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
 4/s 10/10/22.
 09 Days.

total: 1230632
 4/s: 9.850

9850