



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

VEHICLE DETAILS

VEHICLE NO : SKZ71C 2015
 VEHICLE MODEL : MINI COOPER
 CHASSIS NO : WMWXM520302D00729

TP AXA.
 Hui Rong.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT BUMPER <i>Dehd</i>	1	\$ 855.00	\$ 885.00	✓
2	FRONT BUMPER SIDE HOLDER <i>new</i>	2	\$ 58.00	\$ 116.00	+
3	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$ 216.00	\$ 216.00	x.
4	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 445.00	\$ 445.00	✓
5	FRONT BUMPER SPONGE <i>Dehd</i>	1	\$ 149.00	\$ 149.00	✓
6	FRONT BUMPER LOWER GRILLE <i>cutted</i>	1	\$ 220.00	\$ 220.00	✓
7	FRONT BUMPER FOG LAMP <i>new</i>	2	\$ 265.00	\$ 730.00	x.
8	FRONT BUMPER LOWER GARNISH <i>Dehd</i>	1	\$ 315.00	\$ 315.00	✓
9	FRONT BUMPER TOW COVER <i>Dehd</i>	1	\$ 53.00	\$ 53.00	✓
10	FRONT GRILLE <i>cutted</i>	1	\$ 395.00	\$ 395.00	✓
11	HEADLAMP <i>RIT cutted</i>	2	\$ 2,330.00	\$ 4,660.00	2330.
12	HEADLAMP RING <i>RIT new</i>	2	\$ 72.00	\$ 144.00	72
13	BONNET <i>Dented</i>	1	\$ 1,481.00	\$ 1,481.00	1259.
14	BONNET LOCK <i>new</i>	2	\$ 98.00	\$ 196.00	x.
15	BONNET HINGE <i>new</i>	2	\$ 79.00	\$ 158.00	x.
16	BONNET LOGO <i>new</i>	1	\$ 80.00	\$ 80.00	✓
17	FRONT SUPPORT PANEL <i>Repair</i>	1	\$ 425.00	\$ 425.00	x.
18	FRONT SUPPORT PANEL CROSS BAR <i>Bent</i>	1	\$ 75.00	\$ 75.00	✓
19	INTERCOOLER <i>Damaged</i>	1	\$ 1,250.00	\$ 1,250.00	✓
20	AIR CON CONDENSER <i>Dented</i>	1	\$ 782.00	\$ 782.00	✓
21	AIR CON CONDENSER SIDE GUIDE <i>RIT torn</i>	2	\$ 35.00	\$ 70.00	35.
22	RADIATOR <i>Dented</i>	1	\$ 890.00	\$ 890.00	✓
23	RADIATOR FAN ASSY <i>cutted</i>	1	\$ 685.00	\$ 685.00	✓
24	AIR DUCT <i>new</i>	1	\$ 68.00	\$ 68.00	x.
25	FRONT WHEEL ARC GARNISH <i>new</i>	2	\$ 225.00	\$ 450.00	x.
26	REAR BUMPER <i>Dented</i>	1	\$ 947.00	\$ 947.00	✓
27	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 72.00	\$ 144.00	+
28	REAR BUMPER LOWER GARNISH <i>Dehd</i>	1	\$ 341.00	\$ 341.00	✓
29	REAR BUMPER LOWER GARNISH REFLECTOR <i>cutted</i>	1	\$ 82.00	\$ 82.00	✓
30	REAR BUMPER LOWER GARNISH REFLECTOR COVER <i>Dehd</i>	1	\$ 33.00	\$ 33.00	✓
31	REAR BUMPER TOW COVER <i>missing RIT</i>	2	\$ 37.00	\$ 74.00	37.
32	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 411.00	\$ 411.00	✓
33	REAR BUMPER INNER FRAME <i>RIT cutted</i>	2	\$ 165.00	\$ 330.00	165.
34	REVERSE SENSOR <i>2 pieces dent</i>	4	\$ 230.00	\$ 920.00	460
35	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00	✓
36	REAR END PANEL <i>Dented</i>	1	\$ 740.00	\$ 740.00	✓

37	REAR END PANEL TOP GARNISH	NE NE	1	\$ 283.00	\$ 283.00	x.
38	REAR END PANEL AIR VENT	Dented	1	\$ 39.00	\$ 39.00	✓
39	TAILLAMP	RA dented	2	\$ 405.00	\$ 810.00	405
40	TAILLAMP RING	RA dented	2	\$ 40.00	\$ 80.00	40
41	TAILGATE	Dented	1	\$ 1,368.00	\$ 1,368.00	1269
42	TAILGATE LOCK	Dented	1	\$ 268.00	\$ 268.00	✓
43	TAILGATE WEATHERSTRIPE	new	1	\$ 275.00	\$ 159.20	x.
44	TAILGATE INNER TRIM BOARD	cracked	1	\$ 455.00	\$ 455.00	✓
45	TAILGATE OUTER GARNISH	new	1	\$ 310.00	\$ 310.00	x.
46	TAILGATE LOGO	new	1	\$ 59.00	\$ 59.00	✓
47	TAILGATE GLASS MOULDING	new	1	\$ 185.00	\$ 185.00	✓
48	COOPER WORING	new	1	\$ 65.00	\$ 65.00	✓
49	REAR SPEAKER BOARD	new	1	\$ 359.00	\$ 359.00	x.
50	REAR EXHAUST PIPE	Dented	1	\$ 890.00	\$ 890.00	✓
51	REAR EXHAUST PIPE TAIL CHROME	at	1	\$ 140.00	\$ 140.00	✓
52	REAR EXHAUST PIPE MOUNTING	3 m	1	\$ 45.00	\$ 45.00	x.
53	REAR EXHAUST PIPE GASKET	3 m	1	\$ 38.00	\$ 38.00	x.
54	REAR EXHAUST PIPE HEAT SHIELD OUTER	cracked	1	\$ 149.00	\$ 149.00	✓
55	REAR EXHAUST PIPE HEAT SHIELD INNER	cracked	1	\$ 76.00	\$ 76.00	✓
56	REAR FENDER INNER TRIM BOARD	3 m	2	\$ 390.00	\$ 780.00	x.
57	REAR FENDER INNER SHIELD	3 m	2	\$ 205.00	\$ 410.00	x.
58	REAR FENDER WHEEL ARC GARNISH	RA Dented	2	\$ 217.00	\$ 434.00	217.
59	SPARE TYRE PANEL TOP BOARD	Not new	1	\$ 445.00	\$ 445.00	x.

TOTAL PRICE: \$ 26,886.00
 LESS 10% 5% \$ ~~2,688.60~~
 SUB TOTAL PRICE: \$ ~~24,197.40~~

17493
 1661835

1344.30
 2554.7

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL		
1	FRONT NUMBER PLATE	Dented	1	\$ 30.00	\$ 30.00	✓
2	FRONT NUMBER PLATE HOLDER	Dented	1	\$ 30.00	\$ 30.00	✓
3	FRONT BUMPER CLIPS	new	1 SET	\$ 30.00	\$ 30.00	✓
4	FRONT BUMPER STICKER WRAP	new	1	\$ 400.00	\$ 400.00	200.
5	FRONT GRILLE CLIPS	new	1 SET	\$ 20.00	\$ 20.00	✓
6	BONNET STICKER WRAP	new	1	\$ 400.00	\$ 400.00	200
7	AIR CON CONDENSER SIDE GUIDE CLIPS	new	2 SET	\$ 10.00	\$ 20.00	0.
8	RADIATOR COOLANT	new	1	\$ 50.00	\$ 50.00	✓
9	FRONT WHEEL ARC GARNISH CLIPS	new	2 SET	\$ 30.00	\$ 60.00	x.
10	REAR NUMBER PLATE	Dented	1	\$ 30.00	\$ 30.00	✓
11	REAR NUMBER PLATE HOLDER	at	2	\$ 30.00	\$ 30.00	✓
12	REAR BUMPER CLIPS	new	1 SET	\$ 30.00	\$ 30.00	✓
13	REAR BUMPER STICKER WRAP	new	1	\$ 400.00	\$ 400.00	200
14	REAR END PANEL TOP GARNISH CLIPS	new	1 SET	\$ 20.00	\$ 20.00	x.
15	REAR END PANEL SEALANT	new	1 SET	\$ 60.00	\$ 60.00	✓
16	TAILGATE INNER TRIM BOARD CLIPS	new	1 SET	\$ 30.00	\$ 30.00	✓
17	TAILGATE GLASS SEALANT	new	1	\$ 60.00	\$ 60.00	✓
18	TAILGATE STICKER WRAP	new	1	\$ 400.00	\$ 400.00	200.
19	REAR FENDER INNER TRIM BOARD CLIPS	3 m	2 SET	\$ 30.00	\$ 60.00	x.
20	REAR FENDER INNER SHIELD CLIPS	3 m	2 SET	\$ 30.00	\$ 60.00	x.
21	REAR FENDER ARC GARNISH CLIPS	RA + new	2 SET	\$ 30.00	\$ 60.00	20.

TOTAL : \$ 2,280.00

1230

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 2,600.00	1400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1200	
3	WIRING CHECK	\$ 100.00	60	
4	TO APPLY TUFF COAT	\$ 150.00	80	
5	TO REMOVE CONDENSER & TOP UP AIR CON GAS	\$ 120.00	60	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	60	
7	TO REMOVE UPHOLSTRY	\$ 150.00	60	
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
11	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	80	

TOTAL: \$ 5,620.00

3230

ESTIMATE REPORT

TOTAL PARTS COST: \$ ~~26,477.40~~

TOTAL LABOUR COST: \$ 5,620.00

TOTAL REPAIR COST: \$ ~~32,097.40~~

27821.70

33441.70

total: 21078.35

N/S: 16.8k.
124 Days'

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

16.8k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: