

ASS. REC. BY:

REF: CS/CTI 220102220/Dny³

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMA 6182 J Yr Regn: June 2018
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes Benz C180 cc 1595
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 89601 T/Radio: Insured / Std / NI / NA
 Eng/No: 27491031365746
 C/No: WDD2050402R389767
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50 R17
 R: ———

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: P/P % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin
 Front R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 11/10/222 D.O.I. 25/10/222
 Survey held at Accord AMC
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 Rev H/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Chung Taping SJW 2336D
11/11/22	Jimmy # P/P 400.00 with 2 days of pay (Red, 5227.10, 83%)

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) 14/11/22
 Date/Time, File Return to?

Days Of Repair: 2
 Resurvey No. of Trip: 1

Report Format : _____
 Lump Sum / I.B.I: (\$ 400)

Add Fees: Site Insp. (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	
Transportation:	
\$ + \$ = \$	
Photos	
Others	
TOTAL	

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #15-11
 SPRINGLEAF TOWER
 SINGAPORE 079909
 ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 12.10.2022
 VEHICLE NO : SMA6182J
 VEH MAKE/MODEL : MERC C180
 YOM : 2018
 CHASSIS NO : WDD2050402R389767
 DATE OF ACCIDENT : 11.10.2022

NO	QTY	DESCRIPTION	AMOUNT \$
		LIST PRICE:-	
1	1	REAR BUMPER <i>HW</i>	\$ 2,020.00
2	1	REAR BUMPER SIDE RETAINER LH *SHORT <i>SW</i>	\$ 74.00
3	1	REAR BUMPER SIDE RETAINER LH *LONG <i>SW</i>	\$ 75.00
4	1	REAR BUMPER LOWER <i>HW</i>	\$ 275.00
5	1	REAR BUMPER RH EXHAUST CHROME MOULDING <i>HW</i>	\$ 315.00
6	1	REAR BUMPER CENTRE CHROME MOULDING <i>HW</i>	\$ 315.00
7	1	REAR REINFORCMENT BAR <i>HW</i>	\$ 825.00
8	2	REVERSE SENSOR <i>SW</i>	\$ 420.00
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
TOTAL - LIST ITEM			\$ 4,319.00
LIST 10%			\$ 431.90
TOTAL			\$ 3,887.10

X
X
X
X
X
X
X
X

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD #15-11

SPRINGLEAF TOWER

SINGAPORE 079909

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 12.10.2022

VEHICLE NO : SMA6182J

VEH MAKE/MODEL : MERC C180

YOM : 2018

CHASSIS NO : WDD2050402R389767

DATE OF ACCIDENT : 11.10.2022

NO	QTY	DESCRIPTION	AMOUNT \$
SPECIAL NETT ITEMS:-			
1	SET	REAR BUMPER CLIPS <i>SW</i>	\$ 50.00 <i>X</i>
2	SET	REAR FENDER SHIELD CLIPS <i>HW</i>	\$ 50.00 <i>X</i>
3			
4			
5			
6			
7			
8			
Total - SN Item			\$ 100.00
Labour Charges:-			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 600.00 <i>200/-</i>
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 800.00 <i>200/-</i>
3		TO APPLY ANTI RUST TREATMENT	\$ 120.00 <i>HW</i>
		TO REMOVE/REPLACE/REFIX REAR REVERSE SENSOR	\$ 120.00 <i>HW</i>
5			
6			
7			
8			
Total - L/C			\$ 1,640.00
Sub-Total			\$ 5,627.10
7% GST			\$ 393.90
Total			\$ 6,021.00

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

25/10/2022 @ 1030
NA Andu

Acknowledged by Repairer
Signature:
Date:

? Part. 2 days. 97237799 ?/P 400.00
KKK Andu